

WB.15.16.0004 Software Fix List

Contents

[Description](#)

[Product Models](#)

[Enhancements](#)

[Version WB.15.16.0004 Enhancements](#)

[Prerequisites](#)

[Fixes](#)

[Version WB.15.16.0004 Fix List](#)

Description

This fix list covers software versions beginning with WB.15.16.0004.

Version WB.15.16.0004 was the initial release of Major version WB.15.16 software. WB.15.16.0004 software was built from the same source as WB.15.15.0006. WB.15.16.0004 includes all enhancements and fixes in WB.15.15.0006 software, plus the additional enhancements and fixes in the WB.15.16.0004 fix list (below).

Here is a visual depiction of the software sequence, showing how each Major version (for example WB.15.15) is based on the previous Major version - and then additional fixes are added to Minor versions (for example WB.15.15.0007). This depiction shows the three most recent Major versions and all the Minor versions that have been built at the time of this publication.

```
WB.15.14.0002 --> WB.15.14.0006 --> WB.15.14.0007 --> WB.15.14.0008 --> WB.15.14.0009
      |
      | (WB.15.14.0003, .0004, and .0005 were never built)
      v
WB.15.15.0006 --> WB.15.15.0007 --> WB.15.15.0008
      |
      v
WB.15.16.0004
```

These documents are included in the WB.15.16.0004 software zip file:

- Release Notes Basic Information Guide
- WB.15.12.0006 Release Notes
- WB.15.13.0003 Fix List
- WB.15.14.0002 Fix List
- WB.15.15.0006 Fix List
- WB.15.16.0004 Fix List

Product Models

HP 2920-24G Switch	(J9726A)
HP 2920-48G Switch	(J9728A)
HP 2920-24G-PoE+ Switch	(J9727A)
HP 2920-48G-PoE+ Switch	(J9729A)
HP 2920-48G-PoE+ 740W Switch	(J9836A)

Enhancements

Version WB.15.16.0004 Enhancements

Enhancement (CR_0000152339) - BYOD Redirect. The switch can now be configured for BYOD (Bring Your Own Device) Redirect, which sends the device's credentials to a BYOD server such as IMC, that is configured to control network access.

Enhancement (CR_0000124429) - CPU Protection During BPDU flooding. A port can receive a high volume of spanning tree BPDUs when there is a loop in the connected network. This enhancement prevents the switch CPU from being overwhelmed by limiting the rate at which those BPDUs are sent to the CPU. For more information, see the *Advanced Traffic Management Guide* for your switch.

Enhancement (CR_0000128651) - DHCPv4 Server. The switch can now be configured as a DHCPv4 server. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000144107) - DHCPv6 Hardware Addresses. The switch can be configured with option 79 to instruct DHCPv6 relay agents to forward client link-layer addresses. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000137520) - DHCPv6 Snooping and DIPLDv6. DHCPv6 snooping and Dynamic IP Lockdown for IPv6 (DIPLDv6) are now supported. For more information, see the *Access Security Guide* for your switch. These features are not yet supported for YB-software switches.

Enhancement (CR_0000144861) - Generic Header ID in Config File. The switch now allows addition of a generic header ID to configuration files saved on a server. This is used for DHCP Option 67 download requests for configuration files. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000128831) - MAC-Based VLANs (MBV) Enable/Disable. MBV enable/disable options are available using CLI and SNMP. For more information, see the "Web-based and MAC Authentication", and the "Port-Based and User-Based Access Control (802.1X)" chapters in the *Access Security Guide* for your switch.

Enhancement (CR_0000147189) - UDLD Verify Before Forwarding. Unidirectional Link Detection (UDLD) has been enhanced to account for the situation when the link to the directly-connected device is up, but there is no link on one segment of the path to the remote device. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000145339) - VLAN Precedence. Beginning with 15.06 software, if a VLAN is added to a port while authenticated clients are connected to that port, the VLAN addition is delayed until all authenticated clients are disconnected. This enhancement allows a tagged VLAN to be applied immediately to a port that has connected authenticated clients. For more information, see the *Advanced Traffic Management Guide* for your switch.

Prerequisites

BootROM Update Included!

BootROM updates are needed to be able to boot specified switch software versions. In most cases, selected software versions are used to automatically update the BootROM.

This software includes an update to BootROM version WB.15.05. If your switch has an older version of BootROM, the BootROM will be updated with this WB.15.16.0004 software.

During the software update, the switch will automatically boot twice. The switch will update the primary BootROM, then reboot, and then update the secondary BootROM. After the switch flash memory is updated and the final boot is initiated, no additional user intervention is needed. **Do not interrupt power to the switch during this important update.**

Minimum Software Versions

Product Number	Product Name	Minimum Supported Software Version
J9805A	HP 640 Redundant/External PS Shelf	WB.15.13.0003

Fixes

Software fixes are listed in chronological order, from oldest to newest software version. **Unless otherwise noted, each software version listed below includes all the software fixes and enhancements added in previous versions listed below.**

WB.15.11.0003 was the first software version for the HP 2920 switches.

Version WB.15.16.0004 Fix List

Status: Released and fully supported, and posted on the web.

802.1X (CR_0000149780) - Already-authenticated clients that send an EAPOL-Start message are de-authenticated by the switch. This situation happens if the client runs Windows Vista and later operating systems that are set to "include learning".

Authentication (CR_0000148832) - A switch configured with RADIUS authentication for primary login, and local authentication for secondary login fails to use local authentication when RADIUS servers do not respond. In that situation, the switch console is not accessible to valid users.

CLI (CR_0000145136) - When the switch is configured with the **console event critical** setting, the event log output of **show tech all** lists only the critical events. With this fix, **show tech all** lists all event log entries.

CLI (CR_0000145812) - A new command **tcp-push-preserve** is added. This command is enabled by default, and causes TCP packets with the "push" flag to be sent before other packets in the queue. Note that high concentrations of TCP packets with push flags under certain conditions can destabilize your network. Use the **no** form of this command to disable the feature.

CLI (CR_0000148661) - When the output of **show power-over-ethernet brief** displays a Detection Status of either Searching or Delivering for a port, the **show tech all** "poe_status_port all" section displays Other Fault as the "Detect Stat".

CLI (CR_0000149525) - The switch incorrectly allows a user to enable stacking when more than four MSTP instances are configured.

CLI (CR_0000150144) - The output of **show dhcp-relay bootp-gateway vlan <VLAN_number>** gives an incorrect BOOTP Gateway address for VLANs that are not configured for DHCP relay.

CLI (CR_0000152440) - The output of **show tech all** halts while displaying **ImaDbUtil traverseLmaProfTbl**, with the message `=== The command has completed with errors. ===`.

Config (CR_0000149526) - Enabling stacking on a switch that has a trunk configured creates an invalid entry for the trunk in the config file. The resulting configuration file cannot be downloaded to the switch.

Config (CR_0000152757) - After configuring **snmp-server host** on the Commander, stack Member configuration files include two lines with SNMPv3 configuration.

Console (CR_0000148468) - With a console cable connected to a stack member, if the user issues the **show tech all** command and then attempts to cancel the output by entering **<CTRL-C>**, the output pauses but then continues for a long time (up to 30 minutes for a five-member stack). Note that the fix has a small side-effect: Entering **<CTRL-C>** will cause a short delay before the console prompt returns.

Counters (CR_0000149229) - The "Route changes" counter in the output of **show ip rip** increments with every RIP update the router receives, even if there are no route changes.

Counters (CR_0000151412) - The output of a query for meter statistics gives an incorrect value for OpenFlow meter duration.

Counters (CR_0000151415) - The output of a query for port statistics gives an incorrect value for OpenFlow statistics duration.

CPU Utilization (CR_0000151164) - The switch occasionally reports CPU utilization of 99%. This is a false reading and does not affect switch performance.

Crash (CR_0000115372) - The switch might reboot unexpectedly with a message similar to `NMI event SW:IP=0x00000000 MSR:0x00000000 LR:0x00000000 cr: 0x00000000 sp:0x00000000 xer:0x00000000 Task='InetServer' Task ID=0xaad3000`.

Crash (CR_0000146176) - After receiving multiple route changes or route flaps in a short period of time, the switch might reboot unexpectedly with a message similar to `Software exception at krt.c:2134 -- in 'eRouteCtrl', task ID = 0xa9bc400 -> Routing Stack: Assert Failed`.

Crash (CR_0000151102) - In a rare situation, after a failover to the Standby Management Module (SMM) or the stack's Standby switch, the switch might reboot unexpectedly with a message similar to `Software exception at asicMgrSlaveFilters.c:185 -- in 'mNSA', task ID = 0x1b1fea80 -> Internal Name Server Error`.

Crash (CR_0000153386) - When a large number of 802.1X clients are being authenticated, reconfiguring port security modes such as **learn-mode** might cause the switch to reboot unexpectedly with a message similar to `Software exception at multMgmtUtil.c:88 -- in 'mPpmgrCtrl', task ID = 0x13b1f940 -> Internal error`.

Crash (CR_0000154053) - When the switch has 802.1X-authenticated clients on a VLAN and the user deletes that VLAN, the switch might reboot unexpectedly with a message similar to `Software exception at multMgmtUtil.c:151 -- in 'eChassMgr', task ID = 0x3c945800 -> Internal error.`

Crash (CR_0000154769) - With a static IGMP group configured, after issuing the **show run** command, changing the sFlow configuration might cause the switch to reboot unexpectedly with a message similar to `Health Monitor: Restr Mem Access HW Addr=0x60630015 IP=0x1045630 Task='mSnmpCtrl' Task ID=0xa98b4c0 sp:0x47ecc50 lr:0x104a0ac msr: 0x02029200 xer: 0x20000000 cr: 0x48000400.`

Crash Messaging (CR_0000150468) - The crash message includes extraneous text about filing a CR (Change Request).

Enhancement (CR_0000152339) - BYOD Redirect. The switch can now be configured for BYOD (Bring Your Own Device) Redirect, which sends the device's credentials to a BYOD server such as IMC, that is configured to control network access.

Enhancement (CR_0000124429) - CPU Protection During BPDU flooding. A port can receive a high volume of spanning tree BPDUs when there is a loop in the connected network. This enhancement prevents the switch CPU from being overwhelmed by limiting the rate at which those BPDUs are sent to the CPU. For more information, see the *Advanced Traffic Management Guide* for your switch.

Enhancement (CR_0000128651) - DHCPv4 Server. The switch can now be configured as a DHCPv4 server. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000144107) - DHCPv6 Hardware Addresses. The switch can be configured with option 79 to instruct DHCPv6 relay agents to forward client link-layer addresses. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000137520) - DHCPv6 Snooping and DIPLDv6. DHCPv6 snooping and Dynamic IP Lockdown for IPv6 (DIPLDv6) are now supported. For more information, see the *Access Security Guide* for your switch. These features are not yet supported for YB-software switches.

Enhancement (CR_0000144861) - Generic Header ID in Config File. The switch now allows addition of a generic header ID to configuration files saved on a server. This is used for DHCP Option 67 download requests for configuration files. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000128831) - MAC-Based VLANs (MBV) Enable/Disable. MBV enable/disable options are available using CLI and SNMP. For more information, see the "Web-based and MAC Authentication", and the "Port-Based and User-Based Access Control (802.1X)" chapters in the *Access Security Guide* for your switch.

Enhancement (CR_0000147189) - UDLD Verify Before Forwarding. Unidirectional Link Detection (UDLD) has been enhanced to account for the situation when the link to the directly-connected device is up, but there is no link on one segment of the path to the remote device. For more information, see the *Management and Configuration Guide* for your switch.

Enhancement (CR_0000145339) - VLAN Precedence. Beginning with 15.06 software, if a VLAN is added to a port while authenticated clients are connected to that port, the VLAN addition is delayed until all authenticated clients are disconnected. This enhancement allows a tagged VLAN to be applied immediately to a port that has connected authenticated clients. For more information, see the *Advanced Traffic Management Guide* for your switch.

File Transfer (CR_0000145212) - Software downloads via SSL fail with certain browsers, including Internet Explorer versions 7, 8, and 10.

File Transfer (CR_0000148584) - A configuration file with a blank community name in the **snmp-server host** entry cannot be downloaded to the switch. Although the switch does not allow the **snmp-server host** entry to be configured with a blank community name, earlier software bugs might cause this condition.

ICMP (CR_0000155702) - The switch sends a ping request to a random IP address every 20 minutes.

IGMP (CR_0000128678) - In certain topologies the IGMPv2 "Leave Group" from one host can cause the multicast stream to be dropped, even though there are other hosts receiving that stream.

IP Phones (CR_0000137652) - An IP phone that uses the "Automatic Port Synchronization" feature loses its IP address and possibly drops the current call. This has been observed when the switch is configured with the command **cdp mode pre-standard-voice**, and the PC to which the phone is connected goes into hibernation. In that situation the "Automatic Port Synchronization" feature causes the phone to drop and then re-establish link with the switch.

IP Phones (CR_0000147849) - Alcatel phones might reboot unexpectedly when connected to a switch configured to use MAC authentication for IP phones and to use 802.1X authentication for PCs.

IPv6 (CR_0000148594) - IPv6 Router Advertisements that indicate an off-link prefix are not set as "preferred" in the switch, which causes incorrect information in the output of **show ipv6**, and can affect connectivity to hosts that use IPv6 Stateless Address Autoconfiguration. This issue also causes the sFlow "Agent Address" to be listed as 0.0.0.0.

Latency (CR_0000129743) - When the switch receives a high volume of traffic for unknown destinations, the resulting ARPs sent by the switch in combination with other incoming traffic the switch must process can cause latency and dropped packets. In this situation, the event log might report `IpAddrMgr: IPAM Control task delayed due to slave message queues too full`.

Logging (CR_0000146773) - In an IPv4 plus IPv6 environment, upon switch bootup the event log displays the set of source IP policy ("srcip") messages twice. With this fix, IPv6 policy messages are distinguished from IPv4 policy messages.

Logging (CR_0000149891) - When a user disables layer 3 on a VLAN, the event log message might state that layer 3 was disabled for the wrong VLAN.

Logging (CR_0000150244) - Some RMON events are not correctly defined for fault-finder (FFI), SSL, and virus throttling, which causes the switch to report an error such as `system: Unknown Event ID 776` when those events occur.

Management (CR_0000149528) - In some situations with multiple TELNET and/or SSH sessions established, the switch does not accept additional management sessions even if some of the existing ones are killed, responding with the message `Sorry, the maximum number of sessions are active. Try again later`.

Management (CR_0000155717) - After disabling the Out of Band Management (OOBM) interface, saving the config and rebooting the switch, the OOBM interface does not come up even after it is re-enabled.

PoE (CR_0000147518) - After reboot, pre-standard detection of PoE devices does not function correctly on a 2920 or 3800 stack, if the stack commander is a non-PoE switch.

PoE (CR_0000148808) - After disabling PoE on one or more ports, the output of **show cpu slot <slot-number>** shows an increase in CPU utilization of 15% or more.

sFlow (CR_0000147660) - In an IPv6-only environment with Stateless Address Autoconfiguration, sFlow incorrectly uses the link-local address as the agent ID.

SNMP (CR_0000131055) - The MIB object "hpicfDownloadTftpConfig" (1.3.6.1.4.1.11.2.14.11.1.3.5) in switch software has a value of 1 for enabled and 2 for disabled, but the reverse is actually correct. With this fix the MIB object to enable and disable the TFTP client on the switch is changed to "hpicfDownloadTftpClientConfig" (1.3.6.1.4.1.11.2.14.11.1.3.12). Also, the integer values are corrected so 1 is disabled and 2 is enabled.

SNMP (CR_0000149657) - When using the "createAndWait" mode to set parameters via SNMP, multiple RADIUS servers cannot be configured.

SNMP (CR_0000151035) - The switch incorrectly reports that MIB object entPhysicalIsFRU = False for removable fantrays, power supplies, and transceivers.

SNMP (CR_0000154463) - The switch incorrectly reports that MIB object entPhysicalIsFRU = False for transceivers for some switches. This improves the original SNMP fix (CR_0000151035).

Stacking (CR_0000146890) - When the stacking cable is removed from a two-switch stack, both switches show "Stack Status" of Fragment Active.

Stacking (CR_0000154380) - A failover from Commander to Standby with multiple MSTP instances in operation might cause the stack members and connected devices to be unreachable.

Switch Hang (CR_0000154152) - If the switch is sending output to the console at the time the switch is rebooted, the switch might hang and not boot properly.

Web Management (CR_0000149099) - When Spanning Tree Protocol (STP) is enabled via the Web user interface, "mstp" is shown as the default STP mode, and "mstp" is displayed as the operational mode after the user enables STP and saves the change. However, the command line interface shows that the switch operates in "rpvst" mode. Workaround: From the Web user interface, use the dropdown menu to explicitly select "mstp" from the dropdown options, then save the change.

Web Management (CR_0000149777) - After a failover to the Standby Management Module (SMM) or the stack's standby switch, the Web user interface is not accessible via the Out of Band Management (OOBM) port.

