

WB.15.12.0016 Release Notes

Abstract

This document contains supplemental information for the WB.15.12.0016 release.

HP Part Number: 5998-8099
Published: May 2015
Edition: 1



© Copyright 2015 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Acknowledgments

Microsoft®, Windows®, and Windows Server® are trademarks of the Microsoft group of companies.

Contents

1 WB.15.12.0016 Release Notes.....	6
Description.....	6
Version history.....	6
Products supported.....	7
Compatibility/interoperability.....	7
Minimum supported software versions.....	7
Enhancements.....	7
Version WB.15.12.0016.....	8
Version WB.15.12.0015.....	8
Version WB.15.12.0014.....	8
Version WB.15.12.0013.....	8
Version WB.15.12.0012.....	8
Version WB.15.12.0011.....	8
Version WB.15.12.0010.....	8
Version WB.15.12.0009.....	8
Version WB.15.12.0008.....	8
Version WB.15.12.0007.....	8
Version WB.15.12.0006.....	8
CDPv2 Transmit Capability.....	8
Clarify Port VLAN Tagged Status.....	8
Event Log Severity Changes.....	8
Flight Data Recorder Phase 2.....	9
OpenFlow.....	9
RADIUS IPv6.....	9
Readable Interface Names in Traps.....	9
Strict Priority Queueing.....	9
Fixes.....	9
Version WB.15.12.0016.....	9
Authentication.....	9
BPDU Protection.....	9
CLI.....	9
Console.....	10
Counters.....	10
PoE.....	10
RADIUS.....	10
sFlow.....	10
SNMP.....	10
Stacking.....	10
TELNET.....	10
Version WB.15.12.0015.....	10
Config.....	10
Console.....	10
Counters.....	11
Crash.....	11
IGMP.....	11
Mirroring.....	11
Multicast.....	11
Switch Hang.....	11
TELNET.....	12
Version WB.15.12.0014.....	12
BGP.....	12

Counters	12
Crash.....	12
Display Issue	12
Meshing.....	12
RADIUS	12
Spanning Tree.....	12
Version WB.15.12.0013.....	13
Config.....	13
FastBoot.....	13
Version WB.15.12.0012.....	13
Config.....	13
Crash.....	13
Guaranteed Minimum Bandwidth.....	13
ICMP	14
Jumbo Frames.....	14
Policy Based Routing.....	14
sFlow.....	14
TFTP	14
Web Management	14
Version WB.15.12.0011.....	14
Accounting.....	14
DHCP	14
RADIUS Accounting	14
Web Management	14
Version WB.15.12.0010.....	15
CLI.....	15
Config	15
Crash	15
Event Log	15
IGMP	15
Latency	15
Link.....	15
MAC Authentication	16
Menu	16
OpenFlow.....	16
Passwords	16
Routing	16
sFlow.....	16
Web Management	16
Version WB.15.12.0009.....	16
Version WB.15.12.0008.....	16
Authentication.....	16
Banner MOTD.....	16
Crash.....	16
Dynamic ARP Protection.....	17
GVRP	17
IGMP.....	17
Loop Protection	17
Management	17
Passwords	17
SNMP	17
Stacking	17
Transceivers.....	17
Version WB.15.12.0007.....	17
Crash.....	17

Uplink Failure Detection.....	18
Version WB.15.12.0006.....	18
Loop Protection.....	18
SSH.....	18
Upgrade information.....	18
Upgrading restrictions and guidelines.....	18
Contacting HP.....	18
HP security policy.....	18
Related information.....	19
Documents.....	19
Websites.....	19
Documentation feedback.....	19

1 WB.15.12.0016 Release Notes

Description

This release note covers software versions for the WB.15.12 branch of the software.

Version WB.15.12.0006 was the initial release of Major version WB.15.12 software.

WB.15.12.0006 software was built from the same source as WB.15.11.0003. WB.15.12.0006 includes all enhancements and fixes in WB.15.11.0003 software, plus the additional enhancements and fixes in the WB.15.12.0006 enhancements and fixes section of this release note.

Product series supported by this software:

- HP 2920 Switch Series

Version history

All released versions are fully supported by HP, unless noted in the table.

Version number	Release date	Based on	Remarks
WB.15.12.0016	2014-10-06	WB.15.12.0015	Released, fully supported, and posted on the web. Final release of the WB.15.12 branch of software.
WB.15.12.0015	2014-03-14	WB.15.12.0014	Released, fully supported, and posted on the web.
WB.15.12.0014	2014-01-17	WB.15.12.0013	Released, fully supported, and posted on the web.
WB.15.12.0013	2014-11-20	WB.15.12.0012	Released, fully supported, but not posted on the web.
WB.15.12.0012	2013-11-05	WB.15.12.0011	Released, fully supported, but not posted on the web.
WB.15.12.0011	2013-10-10	WB.15.12.0010	Released, fully supported, but not posted on the web.
WB.15.12.0010	2013-08-13	WB.15.12.0008	Released, fully supported, and posted on the web.
WB.15.12.0009	n/a		Never built.
WB.15.12.0008	2013-06-25	WB.15.12.0007	Released, fully supported, but not posted on the web.
WB.15.12.0007	2013-03-27	WB.15.12.0006	Released, fully supported, but not posted on the web.
WB.15.12.0006	2013-02-28	WB.15.11.0003	Released, fully supported, but not posted on the web.
WB.15.11.0009	2013-06-28	WB.15.11.0008	Released, fully supported, but not posted on the web.
WB.15.11.0008	n/a	WB.15.11.0007	Never released.
WB.15.11.0007	2013-03-19	WB.15.11.0006	Released, fully supported, and posted on the web.
WB.15.11.0006	n/a	WB.15.11.0005	Never released.
WB.15.11.0005	n/a	WB.15.11.0004	Never released.

Version number	Release date	Based on	Remarks
WB.15.11.0004	2013-02-04	WB.15.11.0003	Released, fully supported, but not posted on the web.
WB.15.11.0003	2012-12-10	Initial release	Released, fully supported, but not posted on the web.

Products supported

This release applies to the following product models:

Product number	Description
J9726A	HP 2920-24G Switch
J9728A	HP 2920-48G Switch
J9727A	HP 2920-24G-PoE+ Switch
J9729A	HP 2920-48G-PoE+ Switch
J9836A	HP 2920-48G-PoE+ 740W Switch

Compatibility/interoperability

The switch web agent supports the following operating system and web browser combinations:

Operating System	Supported Web Browsers
Windows XP SP3	Internet Explorer 7, 8 Firefox 12
Windows 7	Internet Explorer 9, 10 Firefox 24 Chrome 30
Windows 8	Internet Explorer 9, 10 Firefox 24 Chrome 30
Windows Server 2008 SP2	Internet Explorer 8, 9 Firefox 24
Windows Server 2012	Internet Explorer 9, 10 Firefox 24
Macintosh OS	Firefox 24

Minimum supported software versions

Product number	Product name	Minimum supported software version
J9805A	HP 640 Redundant/External Power Supply Shelf	WB.15.13.0003

Enhancements

This section lists enhancements found in the WB.15.12 branch of the software. Software enhancements are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all enhancements added in earlier versions.

NOTE: The number that precedes the enhancement description is used for tracking purposes.

Version WB.15.12.0016

No enhancements were included in version WB.15.12.0016.

Version WB.15.12.0015

No enhancements were included in version WB.15.12.0015.

Version WB.15.12.0014

No enhancements were included in version WB.15.12.0014.

Version WB.15.12.0013

No enhancements were included in version WB.15.12.0013.

Version WB.15.12.0012

No enhancements were included in version WB.15.12.0012.

Version WB.15.12.0011

No enhancements were included in version WB.15.12.0011.

Version WB.15.12.0010

No enhancements were included in version WB.15.12.0010.

Version WB.15.12.0009

Version WB.15.12.0009 was never built.

Version WB.15.12.0008

No enhancements were included in version WB.15.12.0008.

Version WB.15.12.0007

No enhancements were included in version WB.15.12.0007.

Version WB.15.12.0006

CDPv2 Transmit Capability

CR_0000107011 When a Cisco VoIP phone boots up (or sometimes periodically), it queries the switch and advertises information about itself using CDPv2. The switch receives the VoIP VLAN Query TLV (type 0x0f) from the phone and then immediately sends the voice VLAN ID in a reply packet to the phone using the VLAN Reply TLV (type 0x0e). The phone then begins tagging all packets with the advertised voice VLAN ID.

Clarify Port VLAN Tagged Status.

CR_0000123824 This enhancement allows the identification of ports as access, trunk, or voice. The `show interfaces` command has added the `status` option, which displays tagged and untagged VLAN information for a port. See "Static Virtual LANs (VLANs)" in the *Advanced Traffic Management Guide* for your switch.

Event Log Severity Changes

0000119734 The default severity status of several event log messages has been changed from informational to warning. See the *Event Log Message Reference Guide* for more information about event log messages.

Flight Data Recorder Phase 2

CR_0000106140 The Flight Data Recorder provides a way to capture and preserve data that is related to a crash event. Phase 2 adds the capture and preservation of protocol and subsystem-specific information.

OpenFlow

CR_0000109154 OpenFlow is a programmable open-standard network protocol that uses flexible matching rules to classify and manage network traffic into flows. For more information, see the *OpenFlow Configuration Guide*.

RADIUS IPv6

PR_0000072866, CR_0000077692 This enhancement adds IPv6 capabilities for the RADIUS client. The Network Access Server is now able to use IPv6 addresses as well as communicating with IPv6 RADIUS servers. See "RADIUS Authentication, Authorization, and Accounting" in the *Access Security Guide*. See also the *IPv6 Configuration Guide* for your switch.

Readable Interface Names in Traps

CR_0000113486 The SNMP trap notification messages for linkup and linkdown events on an interface now include IfDesc and IfAlias var-bind information. For more information on SNMP traps, see "Configuring for Network Management Applications" in the *Management and Configuration Guide* for your switch.

Strict Priority Queueing

CR_0000122671 The switches currently implement priority-to-queue mapping as defined in the IEEE 802.1D-2004 Annex G standard. Another standard, IEEE 802.1Q-2005, defines a slightly different mapping where the ordering of priorities 0-2 is changed. This enhancement allows you to configure the switch to follow either standard.

Fixes

Software fixes are listed in reverse-chronological order, from newest to oldest software version. Unless otherwise noted, each software version listed below includes all the software fixes and enhancements added in previous versions listed below.

NOTE: The number that precedes the fix description is used for tracking purposes.

Version WB.15.12.0016

Authentication

CR_0000148832 A switch configured with RADIUS authentication for primary login, and local authentication for secondary login fails to use local authentication when RADIUS servers do not respond. In that situation, the switch console is not accessible to valid users.

BPDU Protection

CR_0000144148 If VLAN 1 is not enabled on the link between a switch running rapid PVST and a switch running any Spanning Tree version, a rapid PVST switch configured for BPDU protection does not shut down the port when it receives a BPDU from the neighboring switch. However, the BPDUs are correctly dropped.

CLI

CR_0000143652 The switch does not allow the `lockout-mac` command to be configured for a MAC address that is all zeros (000000-000000).

Console

CR_0000148864 With a console cable connected to a stack member, if the user issues the `show tech all` command and then attempts to cancel the output by entering `<CTRL-C>`, the output pauses, but then continues for a long time (up to 30 minutes for a five-member stack). Note that the fix has a small side-effect: Entering `<CTRL-C>` causes a short delay before the console prompt returns.

Counters

CR_0000148671 The output of `show ip counters ipv6` gives incorrect values.

PoE

CR_0000147518 After reboot, pre-standard detection of PoE devices does not function correctly on a 2920 or 3800 stack, if the stack commander is a non-PoE switch.

CR_0000148808 After disabling PoE on one or more ports, the output of `show cpu slot <slot-number>` shows an increase in CPU utilization of 15% or more.

RADIUS

CR_0000149657 Configuration of multiple RADIUS servers via SNMP fails if a `createAndWait` mechanism is used.

sFlow

CR_0000147660 In an IPv6-only environment with Stateless Address Autoconfiguration, sFlow incorrectly uses the link-local address as the agent ID.

SNMP

CR_0000147370 After using SNMP to configure a RADIUS server on the switch, the switch does not allow a login until the switch is rebooted.

CR_0000152823 Duplicate RADIUS servers are allowed if the SNMP `createAndWait` mechanism is used.

Stacking

CR_0000146890 When the stacking cable is removed from a two-switch stack, both switches show "Stack Status" of `Fragment Active`.

TELNET

CR_0000142571 While a user is being authenticated by a RADIUS server, issuing the `show access-list radius all` command from a TELNET session might cause the TELNET session to hang.

Version WB.15.12.0015

Config

CR_0000145562 A switch with an active radio port and configured with the command `lldp autoprovision radio-ports auto-vlan 2100` will move the radio ports into VLAN 2101 after a reboot. Similar errors occur for other `auto-vlan` numbers; after reboot the switch creates and uses a new VLAN instead of using the configured VLAN for radio ports.

Console

CR_0000140941 The `console inactivity-timer` setting is applied even if the user is typing on the console, when the console physical connection is to a stack member instead of the commander.

Counters

CR_0000141119 The output of `show ip counters` is incorrect when routing is enabled for IP, IPv6, or multicasts.

CR_0000143860 On a switch configured with rapid PVST and BPDU protection, the output of the command `show spanning-tree bpdu-protection` shows zero errant BPDUs received, even when the switch has disabled a port due to receiving a BPDU. This is a display issue only, both rapid PVST and BPDU protection function properly.

Crash

CR_0000133659 With sFlow enabled and IPv6 configured on a VLAN, the switch might reboot unexpectedly with a message similar to `Software exception at sflow.c:5563 -- in 'mEaseCtrl', task ID = 0x3c8c1680`.

CR_0000142238 From the menu, after selecting **Status and Counters** and **Port Address Table** for an active port, the switch might reboot unexpectedly with a message similar to `Read Error Restr Mem Access HW Addr=0x2020201c IP=0x4ee7ce8 Task='mSess1' Task ID=0xe087cc0 fp: 0x06cefc48 sp:0x06cefc20 cpsr: 0x2000001f dfsr: 0x00000005`.

CR_0000144879 The switch might reboot unexpectedly in the following situations: 1) The switch is running 15.08 or earlier software, is configured to drop frames that have a destination address of 01:00:0c:cc:cc:cd, and has PVST filtering or PVST protection enabled. Then the switch is updated to 15.09 or later software. 2) The switch is running 15.09 or later software, is configured to drop frames that have a destination address of 01:00:0c:cc:cc:cd, and then PVST filtering or PVST protection is enabled. The switch reboots unexpectedly with a message similar to `Software exception at bttfLearn.c:2616 -- in 'mLpmgrCtrl', task ID = 0xa98a9c0 -> Mac Table Error`.

CR_0000146306 The switch uses TCP connections internally for inter-process communication. In a situation where an internal loopback TCP socket pair receives stimulus after an extended period of idle time, the switch might reboot unexpectedly with a message similar to `NMI event SW:IP=0x00e20c1c MSR:0x02029200 LR:0x00e077d0 cr: 0x44000400 sp:0x02b03c58 xer:0x00000000 Task='InetServer' Task ID=0xab31000`.

IGMP

CR_0000138408 Joins sent by clients in response to a Group Specific Query are not forwarded by the Querier, causing the clients to lose the stream.

CR_0000140514 After disabling IGMP forwarding on a port, multicast traffic incorrectly continues to flow from that port.

Mirroring

CR_0000145818 With more than one remote mirroring session configured on a VLAN, if the user deletes a VLAN with a lower number than the VLAN being mirrored, all mirrors except the lowest-numbered mirror session are removed from the mirrored VLAN.

Multicast

CR_0000138817 When a multicast stream is sent to a reserved multicast address, a General Query might not be forwarded by the switch, causing clients to be dropped from the multicast stream.

Switch Hang

CR_0000146247 With both authentication and accounting enabled, the switch might become unresponsive to management, requiring a reboot to recover.

TELNET

CR_0000127908 Continuous logging on and then logging off via TELNET might cause the switch to believe all TELNET sessions are in use, and no additional TELNET sessions can be established.

Version WB.15.12.0014

BGP

CR_0000138230 When BGP has equal cost routes, but one route is preferred due to a higher configured weight, the outputs of `show ip bgp` and `show ip route` show that the router uses the wrong route.

Counters

CR_0000142198 When a trunk configured for sFlow polling is simultaneously queried via SNMP, all counter values for the trunk are zero.

Crash

CR_0000141095 When a switch port is configured for MAC authentication with the `addr-moves` parameter, if a client on that port moves to a different port, the switch might reboot unexpectedly with a message similar to `Software exception at hwBp.c:218 -- in 'fault_handler', task ID = 0xa5df1c0 -> MemWatch Trigger: Offending task 'mWebAuth'. Offending IP=0xb35494.`

CR_0000142134 With outbound queue monitoring configured (`qos watch-queue <PORT>`), a switch module or port bank might reboot unexpectedly with a message similar to `Software exception at alloc_free.c:793 -- in 'mAsicUpd', task ID = 0x61e7b00 -> buf already freed by 0x061E7B00, op=0x00500079.`

CR_0000143459 When a switch is added to a physical stack, if either the new switch or the stack (but not both) is running a version of software listed below, the stack might reboot unexpectedly with a message similar to `Software exception at proStackUtil.c:137 -- in 'mStackingCtrl', task ID = 0x3c940dc0.` The applicable software versions are KA.15.12.0012 (for 3800 switches), and WB.15.12.0012 and WB.15.12.0013 (for 2920 switches).

Display Issue

CR_0000140830 When `terminal length` is changed from the default of 24, the config file display is truncated, and the outputs of `show logging` and `show interfaces` might be interleaved in the output of `show tech all`.

Meshing

CR_0000143068 Multicast traffic and unicast traffic with unknown destination addresses are not routed over the mesh.

RADIUS

CR_0000138258 In some situations, the switch response to Change of Authorization and Disconnect Messages from the RADIUS server is sent from an incorrect source IP address, which the RADIUS server therefore ignores.

Spanning Tree

CR_0000143817 With a switch configured for MSTP, if the spanning tree mode is changed to `force-version rstp-operation` and then a second management module (or stack member) is inserted, the switch might reboot unexpectedly with a message similar to `Health Monitor: Read Error Restr Mem Access HW Addr=0xe59ff10c IP=0x779004c`

Task='mMstpCtrl' Task ID=0x13af9740 fp: 0x0d372620 sp:0x0d372604 cpsr: 0x6000001f.

Version WB.15.12.0013

Config

CR_0000142393 Upgrading software from WB.15.11.xxxx to a newer version changes the console inactivity-timer from the configured value in minutes to that same value in seconds. Also, if the console idletimeout value is set, after reboot the configured value is used for a console connection but not a TELNET connection.

FastBoot

CR_0000141043 If the fastboot setting is changed by the user, and the switch experiences a power interruption or reboot while the new setting is being written to flash, upon bootup the MAC address on a stack member might be erased. Note that this fix has a side effect: If the fastboot setting is changed by the user and the switch software is downgraded (changed to an earlier version), upon bootup the fastboot setting might revert to what it was before the user-initiated change, even though the switch reports that it has been changed. Workaround: Change the fastboot setting twice - first change it back to what it was before the user-initiated change, then change fastboot to the desired setting.

Version WB.15.12.0012

Config

CR_0000138447 After a switch software update, SNMP community access privileges are incorrectly changed by the switch. The output of `show snmp-server` and the output of a `walkmib` command give different results, and neither output represents how the switch actually behaves for Manager or Operator access. This issue was introduced with CR_0000122623; if the access settings were configured on a switch without the CR_0000122623 fix, after updating to software with the CR_0000122623 fix the settings are changed.

Crash

CR_0000135900 In some situations it is possible for the switch to reboot unexpectedly with a message similar to `Software exception at alloc_free.c:646 -- in 'eDrvPoll', task ID = 0xa9a7a80 -> buf already freed by 0x0A9A7D40, op=0x0006003E`.

CR_0000137288 With SNTP configured, in a rare situation after a time update, the switch might reboot unexpectedly with a message similar to `Health Monitor: Invalid Instr Misaligned Mem Access HW Addr=0x31352e30 IP=0x31352e30 Task='mDebugCtrl' Task ID=0x3c9558c0 sp:0x11f92cd0 lr:0x31352e31 msr: 0x02029200 xer: 0x00000000 cr: 0x28000800`.

CR_0000138879 After boot, a switch that has a syslog server and an IPv6 address configured might become unresponsive to management, and after a period of time the switch might reboot repeatedly with a message similar to `NMI event SW:IP=0x001517d4 MSR:0x02029200 LR:0x0015178c cr: 0x28000400 sp:0x03aae0e0 xer:0x00000000 Task='mDebugCtrl' Task ID=0xa9f8000`.

Guaranteed Minimum Bandwidth

CR_0000136039 When the switch is configured to use fewer than the default of 8 queues, packets in lower-priority queues might be unintentionally dropped.

ICMP

CR_0000134682 The switch does not log an unsolicited ICMP reply unless it has first pinged some (any) IP address. Also, unsolicited ICMP reply log messages are sometimes associated with the DEFAULT_VLAN instead of the VLAN of the incoming unsolicited ICMP reply.

Jumbo Frames

CR_0000137961 When jumbo frames are enabled on any VLAN, OSPF fails to establish an adjacency after a switch reboot, and RIP updates might not be accepted by the router.

Policy Based Routing

CR_0000134936 The show statistics policy counter is not reset by the `clear statistics policy` command.

sFlow

CR_0000134427 sFlow sampling of multicast packets sometimes results in duplicate packets that can cause pixelation of video or other degradation of the multicast stream.

TFTP

CR_0000132721 Certain lines in the configuration file are sometimes incorrectly changed when imported via TFTP. For example, the configuration entry `snmp-server community public unrestricted` might have the `unrestricted` parameter removed when the config file is downloaded via TFTP.

Web Management

CR_0000139666 Customers using a browser that does not support the X-Frame-Options tag, and who have an open Web management session and then initiate another browser session, could be vulnerable to cross-frame scripting.

CR_0000140379 A self-signed SSL certificate and a CA-generated certificate cannot use an organizationName, organizationalUnitName, localityName, stateOrProvinceName longer than 40 characters. With this fix, the limit is 64 characters.

Version WB.15.12.0011

Accounting

CR_0000133762 If a Windows system is configured for both computer authentication and user authentication, accounting might not function properly.

DHCP

CR_0000137877 A switch acting as a DHCP relay agent sends two DHCP packets, one of which incorrectly has the source MAC address of the client instead of the switch.

RADIUS Accounting

CR_0000137793 An interim-update status request generates incorrect accounting information in the RADIUS server.

Web Management

CR_0000137792 A self-signed SSL certificate generated via the Web interface cannot use a common name (CN) longer than 40 characters. With this fix, the limit is 90 characters.

Version WB.15.12.0010

CLI

CR_0000137287 The output of `show run vlan <VLAN_ID>` omits the `no` in the configuration entry `no ip igmp fastleave`. Note that the output of `show run` gives correct information.

Config

CR_0000131054 Setting an operator or manager password on the switch causes four features to be disabled: auto run, DHCP-based config file download from an external tftp server, DHCP-based software image download from an external tftp server, and tftp server functionality within the switch. With this fix, more accurate messages are sent regarding the specific features that are disabled by setting the operator or manager password.

CR_0000135481 After boot, a config file that has a trap destination community name with an open parenthesis "(" or a close parenthesis ")" cannot be downloaded to the switch.

Crash

CR_0000127791 In a rare situation the switch might reboot unexpectedly with a message similar to `Software exception at rt_table.c:`

CR_0000130339 In some situations, executing the command `show snmp-server traps` might cause the switch to reboot unexpectedly with a message similar to `Software exception at cli_snmpv2_action.c:9634 -- in mSess2', task ID = 0x13ab0 -> ASSERT: failed.`

CR_0000131604 Configuring Mac Authentication with a 256-client limit might cause the switch or stack member to reboot unexpectedly.

CR_0000131959 With MAC Authentication configured on stacking ports, the switch might reboot unexpectedly with a message similar to `Software exception at highAvailHelper.c:1040 -- in 'mRdHelper', task ID = 0x3c9389c0.`

Event Log

CR_0000127436 After the switch uptime reaches 497 days, the timestamp entries in the event log become erratic with gaps of several hours or days. In some cases the timestamps revert to previous months and years, even though SNTP updates with those wrong timestamps report the correct date and time.

IGMP

CR_0000132149 Although the RFC requires that the switch with the lowest IP address becomes querier, a switch that is acting as querier stops being querier when it receives a query from a switch with a higher IP address.

CR_0000135527 A non-querier switch that receives a Join from the querier fails to send further Joins to the querier, resulting in loss of multicast traffic.

Latency

CR_0000132667 After a switch reboot, traffic that flows through the J9538A 8-port 10GbE SFP+ v2 zl Module experiences poor performance.

Link

CR_0000137549 Gigabit fiber transceivers operate in auto-negotiation mode even if the port is configured for 1000 Mbps full-duplex operation (`speed-duplex 1000-full`). If both sides of the link are configured as 1000-full, the link goes down after the switch at one side of the link is updated with affected software. This issue was introduced in software version 15.12.0006.

MAC Authentication

CR_0000129991 MAC Authentication fails when the `peap-mschapv2` parameter is included in the `aaa authentication` CLI command.

Menu

CR_0000135171 With the Menu interface, if the user navigates to **Switch Configuration** → **IP Configuration** and selects **Save** without changing anything on that screen, OSPF settings are removed from every VLAN.

OpenFlow

CR_0000134471 OpenFlow flows are not programmed correctly when RPVST+ is disabled on the OpenFlow member VLAN.

Passwords

CR_0000134358 Navigating to the security wizard page on a switch that has manager and operator credentials set, a tool such as firebug allows the admin to view passwords in the `secwiz.js` file. (The admin would have to be logged in with valid credentials to view the passwords.)

Routing

CR_0000123230 The switch does not forward traffic to a host that has a static route configured with a 32-bit subnet mask. Traces show that the switch never sends an ARP request for that host.

sFlow

CR_0000128439 When an sFlow-sampled inbound packet is to be routed, the sFlow data gives the wrong output port on the switch.

Web Management

CR_0000135883 The **Rx Errors** column is missing from the Web user interface.

Version WB.15.12.0009

Version WB.15.12.0009 was never built.

Version WB.15.12.0008

Authentication

CR_0000134114 With both 802.1X and MAC Authentication configured on a port, it is possible for an already-authenticated client to be erroneously moved to the unauthenticated VLAN.

Banner MOTD

CR_0000132198 The login banner is not displayed if the user logs into the switch via the standby or member switch instead of the active or commander switch.

Crash

CR_0000126777 With a combination of interface state changes along with IPV6 address configuration changes, it is possible for the switch to reboot unexpectedly with a message similar to `SubSystem 0 went down: 01/24/13 13:31:29, Invalid Instr HW Addr=0x000004a8 IP=0x4a8, Task='mIpCtrl' Task ID=0xa9ca140 sp:0x470aab0 lr:0x723f4c, msr: 0x02029200 xer: 0x20000000 cr: 0x48000400.`

CR_0000129047 When running commands from multiple simultaneous CLI sessions the switch may reboot with the error message `Software exception at hwBp.c:218.`

Dynamic ARP Protection

CR_0000132073 When a VLAN is configured for dynamic ARP protection and also DHCP snooping, ARP packets should be forwarded, but are incorrectly dropped when the `arp-protect` configuration does not include the `validate ip` option.

GVRP

CR_0000129917 When the switch receives its own GVRP frames, it learns from them instead of dropping the frames.

CR_0000130090 After rebooting the switch, the configuration `unknown-vlans disable` does not work on trunks.

IGMP

CR_0000134412 The switch sends an IGMP General Query with an incorrect layer 2 destination address.

Loop Protection

CR_0000127150 Loop protection fails to detect a loop on a port configured for 802.1X authentication, if 802.1X is not enabled globally.

Management

CR_0000134091 Disabling write access to an SNMP community via the Web user interface might cause the switch to become unresponsive to command input. The switch must be rebooted to regain management access.

Passwords

CR_0000130921 If the switch is configured with a username and password, changing the password causes the username to also change. The username is changed to the default `manager` or `operator`, depending on which password is changed.

CR_0000134675 The switch does not automatically create a default username of `manager` or `operator` when a password is configured for those levels of access.

SNMP

CR_0000122623 After rebooting a switch configured for SNMP with the parameters `operator unrestricted`, the switch does not allow the user to set any read/write MIB objects.

Stacking

CR_0000121075 When stacking is enabled, the switch is accessible via the Web even after disabling the Web server, and via TELNET even after disabling TELNET.

Transceivers

CR_0000133023 100-Megabit transceivers might have one or more of these symptoms: 1) Link LED is lit but link is down, 2) No Link after the transceiver is hot-swapped, 3) Transceiver fails self test.

Version WB.15.12.0007

Crash

CR_0000127335 In some situations, issuing the `show tech all` command might cause the switch to reboot unexpectedly with a message similar to `Length Corruption`.

Uplink Failure Detection

CR_0000127868 On a switch that is configured for uplink failure detection where the link to monitor (LtM) or link to disable (LtD) is an LACP trunk, after reboot the link to monitor is listed as down in the output of `show uplink-failure-detection`, and the link to disable is taken down by the switch.

Version WB.15.12.0006

Loop Protection

CR_0000109506 In some cases, loop protection fails to disable the port.

SSH

PR_0000072707, CR_0000077550 The switch allows unlimited SSH connection attempts. With this fix, the switch's SSH server goes into a 60-second timeout period after three consecutive unsuccessful login attempts.

Upgrade information

Upgrading restrictions and guidelines

WB.15.12.0016 uses BootROM WB.15.04. If your switch has an older version of BootROM, the BootROM will be updated with this version of software.

For more information about BootROM, see the *HP Switch Software Management and Configuration Guide* for your switch.

-
- ⓘ **IMPORTANT:** During the software update, the switch will automatically boot twice. The switch will update the primary BootROM, then reboot, and then update the secondary BootROM. After the switch flash memory is updated and the final boot is initiated, no additional user intervention is needed. Do not interrupt power to the switch during this important update.
-

Contacting HP

For additional information or assistance, contact HP Networking Support:

www.hp.com/networking/support

Before contacting HP, collect the following information:

- Product model names and numbers
- Technical support registration number (if applicable)
- Product serial numbers
- Error messages
- Operating system type and revision level
- Detailed questions

HP security policy

A Security Bulletin is the first published notification of security vulnerabilities and is the only communication vehicle for security vulnerabilities.

- Fixes for security vulnerabilities are not documented in manuals, release notes, or other forms of product documentation.
- A Security Bulletin is released when all vulnerable products still in support life have publicly available images that contain the fix for the security vulnerability.

To find security bulletins:

1. Go to the HP Support Center website at www.hp.com/go/hpsc.
2. Enter your product name or number and click **Go**.
3. Select your product from the list of results.
4. Click the **Top issues & solutions** tab.
5. Click the **Advisories, bulletins & notices** link.

To initiate a subscription to receive future HP Security Bulletin alerts via email, sign up at: www4.hp.com/signup_alerts

Related information

Documents

To find related documents, see the HP Support Center website:

www.hp.com/support/manuals

- Enter your product name or number and click **Go**. If necessary, select your product from the resulting list.
- For a complete list of acronyms and their definitions, see *HP FlexNetwork Technology Acronyms*.

Related documents

The following documents provide related information:

- *HP Switch Software Basic Operation Guide*
- *HP Switch Software Feature Index — Enabled*

Websites

- Official HP Home page: www.hp.com
- HP Networking: www.hp.com/go/networking
- HP product manuals: www.hp.com/support/manuals
- HP download drivers and software: www.hp.com/networking/software
- HP software depot: www.software.hp.com
- HP education services: www.hp.com/learn

Documentation feedback

HP is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback (docsfeedback@hp.com). Include the document title and part number, version number, or the URL when submitting your feedback.