

YA/YB.15.17.0007 Release Notes

Abstract

This document contains supplemental information for the YA/YB.15.17.0007 release.

HP Part Number: 5998-8456
Published: June 2015
Edition: 1



© Copyright 2015 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Acknowledgments

Microsoft®, Windows®, and Windows Server® are U.S. registered trademarks of the Microsoft group of companies.

Contents

1	YA/YB.15.17.0007 Release Notes.....	5
	Description.....	5
	Important information.....	5
	Version history.....	5
	Products supported.....	6
	Compatibility/interoperability.....	6
	Minimum supported software versions for hardware products.....	7
	Enhancements.....	7
	Version YA/YB.15.17.0007.....	8
	Version YA/YB.15.17.0006.....	8
	Version YA/YB.15.17.0005.....	8
	Version YA/YB.15.17.0004.....	8
	Configurable TLS.....	8
	Version YA/YB.15.17.0003.....	8
	DLDP.....	8
	RADIUS.....	8
	TACACS.....	8
	Trust Anchor Certificates.....	9
	Fixes.....	9
	Version YA/YB.15.17.0007.....	9
	File Transfer.....	9
	Version YA/YB.15.17.0006.....	9
	CLI.....	9
	Config.....	9
	Crash.....	9
	Display Issue.....	9
	Event Log.....	10
	Flow Control.....	10
	Link.....	10
	Logging.....	10
	PIM.....	10
	Security Vulnerability.....	10
	sFlow.....	10
	Stacking.....	10
	Transceivers.....	10
	Version YA/YB.15.17.0005.....	11
	Version YA/YB.15.17.0004.....	11
	CLI.....	11
	Crash.....	11
	Logging.....	11
	Memory.....	12
	RADIUS.....	12
	TFTP.....	12
	Version YA/YB.15.17.0003.....	12
	802.1X.....	12
	Authentication.....	12
	CLI.....	12
	CPU Utilization.....	13
	Crash.....	13
	Display Issue.....	13
	File Transfer.....	13

ICMP.....	13
IPv6.....	13
LLDP.....	13
Logging.....	14
MDI.....	14
Multicast.....	14
Multiple Symptoms.....	14
PoE.....	14
Port Connectivity.....	14
RADIUS.....	14
Routing.....	14
Self Test.....	14
SNMP.....	14
SSL.....	15
SSH.....	15
Stacking.....	15
Switch Hang.....	15
Web Management.....	15
Upgrade information.....	15
Upgrading restrictions and guidelines.....	15
Contacting HP.....	15
HP security policy.....	16
Related information.....	16
Documents.....	16
Websites.....	17
Documentation feedback.....	17

1 YA/YB.15.17.0007 Release Notes

Description

This release note covers software versions for the YA/YB.15.17 branch of the software.

Version YA/YB.15.17.0003 was the initial build of Major version YA/YB.15.17 software.

YA/YB.15.17.0007 includes all enhancements and fixes in the YA/YB.15.16.0004 software, plus the additional enhancements and fixes in the YA/YB.15.17.0003 enhancements and fixes sections of this release note.

Product series supported by this software:

- HP 2530 Switch Series

Important information

To avoid damage to your equipment, do not interrupt power to the switch during a software update.

Version history

All released versions are fully supported by HP, unless noted in the table.

Version number	Release date	Based on	Remarks
YA/YB.15.17.0007	2015-06-22	YA/YB.15.17.0006	Released, fully supported, and posted on the web.
YA/YB.15.17.0006	n/a	YA/YB.15.17.0005	Never released.
YA/YB.15.17.0005	n/a	YA/YB.15.17.0004	Never released.
YA/YB.15.17.0004	2015-04-23	YA/YB.15.17.0003	Released, fully supported, but not posted on the web.
YA/YB.15.17.0003	n/a	YA/YB.15.16.0004	Never released.
YA/YB.15.16.0009	2015-06-16	YA/YB.15.16.0008	Please see the YA/YB.15.16.0009 release note for detailed information on the YA/YB.15.16 branch. Released, fully supported, and posted on the web.
YA/YB.15.16.0008	2015-04-17	YA/YB.15.16.0007	Released, fully supported, and posted on the web.
YA/YB.15.16.0007	n/a	YA/YB.15.16.0006	Never released.
YA/YB.15.16.0006	2015-02-06	YA/YB.15.16.0005	Released, fully supported, and posted on the web.
YA/YB.15.16.0005	2014-11-21	YA/YB.15.16.0004	Released, fully supported, and posted on the web.
YA/YB.15.16.0004	2014-10-30	YA/YB.15.15.0006	Initial release of YA/YB.15.16. Released, but never posted on the web.
YA/YB.15.15.0013	2015-06-16	YA/YB.15.15.0012	Please see the YA/YB.15.15.0013 release note for detailed information on the YA/YB.15.15 branch. Released, fully supported, and posted on the web.
YA/YB.15.15.0012	2015-04-17	YA/YB.15.15.0011	Released, fully supported, and posted on the web.

Version number	Release date	Based on	Remarks
YA/YB.15.15.0011	n/a	YA/YB.15.15.0010	Never released.
YA/YB.15.15.0010	2015-02-06	YA/YB.15.15.0009	Released, fully supported, and posted on the web.
YA/YB.15.15.0009	2015-01-07	YA/YB.15.15.0008	Released, fully supported, and posted on the web.
YA/YB.15.15.0008	2014-09-15	YA/YB.15.15.0007	Released, fully supported, and posted on the web.
YA/YB.15.15.0007	2014-06-26	YA/YB.15.15.0006	Released, fully supported, but not posted on the web.
YA/YB.15.15.0006	2014-03-19	YA/YB.15.14.0002	Initial release of YA/YB.15.15. Released, fully supported, and posted on the web for early availability.

Products supported

This release applies to the following product models:

Product number	Description
J9783A	HP 2530-8 Switch
J9782A	HP 2530-24 Switch
J9781A	HP 2530-48 Switch
J9777A	HP 2530-8G Switch
J9776A	HP 2530-24G Switch
J9775A	HP 2530-48G Switch
J9780A	HP 2530-8-PoE+ Switch
J9779A	HP 2530-24-PoE+ Switch
J9778A	HP 2530-48-PoE+ Switch
J9774A	HP 2530-8G-PoE+ Switch
J9773A	HP 2530-24G-PoE+ Switch
J9772A	HP 2530-48G-PoE+ Switch
JL070A	HP 2530-8-PoE+ Internal Power Supply Switch
J9856A	HP 2530-24G-2SFP+ Switch
J9855A	HP 2530-48G-2SFP+ Switch
J9854A	HP 2530-24G-PoE+-2SFP+ Switch
J9853A	HP 2530-48G-PoE+-2SFP+ Switch

Compatibility/interoperability

The switch web agent supports the following operating system and web browser combinations:

Operating System	Supported Web Browsers
Windows XP SP3	Internet Explorer 7, 8

Operating System	Supported Web Browsers
	Firefox 12
Windows 7	Internet Explorer 9, 10 Firefox 24 Chrome 30
Windows 8	Internet Explorer 9, 10 Firefox 24 Chrome 30
Windows Server 2008 SP2	Internet Explorer 8, 9 Firefox 24
Windows Server 2012	Internet Explorer 9, 10 Firefox 24
Macintosh OS	Firefox 24

Minimum supported software versions for hardware products

NOTE: If your switch or module is not listed in the below table, it runs on all versions of the software.

Product number	Product name	Minimum software version
J9856A	HP 2530-24G-2SFP+ Switch	YA.15.15.0006
J9855A	HP 2530-48G-2SFP+ Switch	YA.15.15.0006
J9854A	HP 2530-24G-PoE+-2SFP+ Switch	YA.15.15.0006
J9853A	HP 2530-48G-PoE+-2SFP+ Switch	YA.15.15.0006
J9783A	HP 2530-8 Switch	YB.15.12.0006
J9782A	HP 2530-24 Switch	YB.15.12.0006
J9780A	HP 2530-8-PoE+ Switch	YB.15.12.0006
J9779A	HP 2530-24-PoE+ Switch	YB.15.12.0006
J9781A	HP 2530-48 Switch	YA.15.12.0006
J9778A	HP 2530-48-PoE+ Switch	YA.15.12.0006
J9777A	HP 2530-8G Switch	YA.15.12.0006
J9774A	HP 2530-8G-PoE+ Switch	YA.15.12.0006
J9776A	HP 2530-24G Switch	YA.15.10.0003
J9775A	HP 2530-48G Switch	YA.15.10.0003
J9773A	HP 2530-24G-PoE+ Switch	YA.15.10.0003
J9772A	HP 2530-48G-PoE+ Switch	YA.15.10.0003

Enhancements

This section lists enhancements found in the YA/YB.15.17 branch of the software. Software enhancements are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all enhancements added in earlier versions.

NOTE: The number preceding the enhancement description is used for tracking purposes.

Version YA/YB.15.17.0007

No enhancements are included in version YA/YB.15.17.0007.

Version YA/YB.15.17.0006

No enhancements were included in version YA/YB.15.17.0006.

Version YA/YB.15.17.0005

No enhancements were included in version YA/YB.15.17.0005.

Version YA/YB.15.17.0004

Configurable TLS

CR_0000160085 Configurable TLS version and enforcing the use of a specific cipher suite.

The National Institute of Standard and Technology (NIST) has provided requirements for the use of TLS in Special Publication 800-52. These requirements state that a minimum version of TLS must be enforced, as well as the use of specific cipher suites. In order to meet these requirements, the software has been modified to support enforcing minimum versions of TLS and specify which cipher suites are to be used.

As a TLS client, the switch will advertise the configured preferences for the TLS version and cipher suite to the server. If the server does not support the cipher suite or negotiates a lower TLS version, the connection between client and server will be terminated. As an HTTPS server, the switch will check the TLS version and cipher suite advertised by the client. Should it detect a mismatch with the configured TS version or cipher suite for the application, the connection will be terminated.

The following new CLI command has been implemented in order to configure the minimum TS version and cipher suite:

```
[no] tls application { web-ssl | openflow | syslog | tr69 | all }
```

```
lowest-version { tls1.0 | tls 1.1 | tls 1.2 | default }
```

```
cipher { aes256-sha256 | aes256-sha | aes128-sha256 | aes128-sha |  
des3-cbc-sha | ecdh-rsa-aes128-gcm-sha256 }
```

The MIB HP-ICF-TLS-MIN-MIB (OID string: 1.3.6.1.4.1.11.2.14.11.5.1.112) has been implemented to provide support for the feature via SNMP.

Version YA/YB.15.17.0003

DLDP

Device Link Detection Protocol (DLDP) is a feature that can detect unidirectional link status in a fiber or twisted pair cable, so that the link can be shut down. This feature is in Comware-based switches and is similar to the existing UDLD feature in ProVision switches. For more information, see the *HP Switch Software Basic Operation Guide*.

RADIUS

RADIUS filter-id allows RADIUS to better support IMC policy interoperability. For more information, see the *HP Switch Software Access Security Guide*.

TACACS

Addition of accounting to the existing TACACS+ authentication capability. For more information, see the *HP Switch Software Access Security Guide*.

Trust Anchor Certificates

CR_0000156165 Basic Constraint Extension `pathlenConstraint` support added to Certificate Manager In software versions 15.14 and later, support was added for Trust Anchor (TA) certificates, which allow a user to sign intermediate Trust Anchor certificates or an end entity certificate. In section 4.2.1.9, RFC 5820 defines a Basic Constraint Extension named `pathlenConstraint` as the field that defines "...the maximum number of non-self-issued intermediate certificates that may follow this certificate in a valid certification path. ...A `pathlenConstraint` of zero indicates that no non-self-issued intermediate CA certificates may follow in a valid certification path. Where it appears, the `pathlenConstraint` field MUST be greater than or equal to zero. Where `pathlenConstraint` does not appear, no limit is imposed." Support for the `pathlenConstraint` has been added to the software. It can be set to the maximum value of 3 because the software supports up to 3 intermediate certificates. When it is set to 0, it can only sign an end entity certificate and not another intermediate certificate.

Fixes

This section lists released builds that include fixes. Software fixes are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all fixes added in earlier versions.

NOTE: The number that precedes the fix description is used for tracking purposes.

Version YA/YB.15.17.0007

File Transfer

CR_0000172816 The switch might reboot unexpectedly (crash) after using TFTP/SFTP file transfer to download software if the switch is not rebooted immediately afterwards. Workaround: reboot after every TFTP/SFTP download.

Version YA/YB.15.17.0006

CLI

CR_0000172046 The commands `show lldp info local-device` and `show lldp info remote-device` sometimes fail to display the correct information when the switch is not connected to any remote device.

Config

CR_0000170324 When a change is made from the CLI in the **Switch Configuration – Port/Trunk Settings** menu, the change is not saved, resulting in an `Unable to save field error`.

Crash

CR_0000164064 When a free radius authenticated user attempts to HTTPS to the switch web management GUI of the 2530-24G, the switch crashes with `Health Monitor: Read Error Restr Mem Access Task='tHttpd'`.

CR_0000168194 The switch might restart with an error message similar to the following during a session logout, kill, or timeout: `Software exception crash at multMgmtUtil.c:151 -- in 'mOobmCtrl', task ID = 0x13b15e00-> Internal error.`

Display Issue

CR_0000167906 When the alert log is sorted by date/time, items are sorted (erroneously) alphabetically by day of the week, rather than day of the month.

Event Log

CR_0000171023 During incorrect login attempts, a message is only logged to the event log after 3 attempts. A change has been made to log incorrect username/password attempt after *each* occurrence.

Flow Control

CR_0000169712 When flow-control is enabled, or enabled and then disabled, it erroneously causes a BDPU starvation condition. Symptoms include multiple BDPU starvation messages in the log, the switch declaring itself ROOT, unblocking of any blocked ports, and layer 2 loops.

Link

CR_0000169819 When the switch is configured for Rapid-PVST (RPVST), any changes to port path cost takes effect properly. However, when the port is disabled and then re-enabled, the port path cost applied and also advertised to neighbors changes to the default path cost.

Logging

CR_0000155070 The Alert-Log filter criteria do not work as expected when a substring is used as a filter.

CR_0000171737 After logging in to the switch using Operator credentials, and the enable command is then executed with incorrect Manager credentials, the event log erroneously shows the session belonged to Manager username.

CR_0000172072 Event log `show log -r` does not show an invalid key attempt during an SSH Public Key Login Failure.

PIM

CR_0000169557 Under certain conditions, an IGMP stream freezes for all in the group. Two examples known to cause this are:

1. When a client directly attached to Core 1 sends a LEAVE for a Group that it is streaming, all other clients watching that Group freeze, until either a GQ is sent out for that Group, or another client sends a new Join for that group, after which all other clients resume streaming that group again.
2. When there are clients directly attached to Core 2, the LAST leave causes clients directly connected to Core 1 to freeze.

Security Vulnerability

CR_0000166717 Login is permitted with the default username Manager, even when the Manager username has been changed to a custom username.

sFlow

CR_0000168606 Switch 5400R continues to send incorrect sFlow datagrams for non-existent ports after removing the module associated with these ports.

Stacking

CR_0000170433 In a stacked configuration, if the MAC Authentication password is set to a password of exactly 16 characters (max length) and configuration is saved, when the stack reboots, the member switch hangs during reboot.

Transceivers

CR_0000163290 Some SR J9150A and LRM J9152A transceivers show as NON-HP with K.15.07 and W.15.07 software.

Version YA/YB.15.17.0005

Version YA/YB.15.17.0005 was never released.

Version YA/YB.15.17.0004

CLI

CR_0000167157 The 2910al CLI command `show interface transceiver detail` indicates the wrong value for the maximum allowed distance for the J4858C X121 1G SFP LC SX transceiver.

Crash

CR_0000155066 The switch may reboot unexpectedly with a Software Exception message similar to: `Software exception at stackingFile.c:2224 -- in 'mStackDatWriter', task ID = 0x3c953b00 -> Internal Error ID: 6382d706`) when a lot of TFTP file transfers to an external TFTP server have occurred.

CR_0000162155 Configuring an OpenFlow instance using secure mode, enabling OpenFlow, and then configuring the lowest-version for OpenFlow may cause the switch to reboot unexpectedly. Other triggers include updating the `tls lowest-version` for an app for which a cipher is already configured, and executing the `no tls app <app> lowest-version <ver> cipher` CLI command. The crash message references a mem-watch trigger.

CR_0000162400 When the switch continuously attempts to transfer a file to a destination that returns an error, for example because it ran out of space to store the file, the switch might eventually crash with the following message: `Software exception at hwBp.c:218 -- in 'fault_handler', task ID = 0x3c403380 -> MemWatch Trigger: Offending task 'mftTask'.`

CR_0000166340 An SNMP crash occurs during PCM discovery on 2620 and 2650, if an Avaya phone is connected to the switch that advertises an organizational OUI value 00-00-00 (all zeros), or any neighbor entry contains an all zero OUI type TLV, during walkmib on the switch. Workaround: Change the lldp admin status to `txOn1y` on the link that is connected to the specific Avaya phone.

CR_0000167603 After issuing the command `crypto key generate auto-run`, the system requires time to generate the key-pair. When the software is still busy processing the task and the command `crypto key generate ssh` is entered, the switch crashed with the following message: `Software exception at rsa_key_generator.c:750 -- in 'mSess1', task ID = 0xa99c9c0 -> rsa key creation.`

CR_0000167916 Within the same uptime/boot period, if DHCP is enabled/disabled multiple times, the following symptoms could be seen:

- Crash
- File transfer failure
- Loss of IP communication

CR_0000169893 The switch reboots unexpectedly (crashes) if a user attempts to replace an ACL or QoS policy on multiple ports if an ACL or policy is already applied to some, but not all of the ports where the new ACL or policy is being applied.

CR_0000169920 Using the `copy support-log` command on rare occasions might cause the switch to crash with unexpected crash messages.

Logging

CR_0000167753 When trying to apply the command `logging system-module acct`, the switch sends the error message: `C1-3500(config)# logging system-module acct Invalid value.`

Memory

CR_0000168160, CR_0000169917 Switch may crash in an unknown state over a very long period when a rare set of CLI operations occur.

CR_0000169918 Switch leaks a small amount of memory during initialization, which results in a reduced amount of available memory being reported by `show system`.

CR_0000169919 Switch may crash in an unknown state over a very long period when a rare set of SNMP operations occur.

RADIUS

CR_0000167582 RADIUS client authentication succeeds even after maximum ACE rules (1024) have been reached.

TFTP

CR_0000159058 When the switch is used as TFTP server and configuration files are transferred from the switch to an external TFTP client, the software creates a temporary file in memory that is removed after the transfer has completed. However, the temporary file is not deleted when an error occurs during the file transfer. When repeated transfers of configuration files fail, the temporary files accumulate and might deplete the available memory space. Once depleted, further file transfers fail and the switch might reboot unexpectedly (crash). Note that when the switch is rebooted, all temporary files are removed from memory.

Version YA/YB.15.17.0003

802.1X

CR_0000149780 The fix in CR 0000133762 causes Microsoft's Roaming User Profile feature to fail to work properly.

CR_0000164489 802.1x re-authentication period works if the client connects after the switch is booted. If, however, the switch reboots while clients are connected, it authenticates initially, but no re-authentication occurs.

Authentication

CR_0000156072 When generating a self-signed certificate or Certificate Sign Request (CSR) in the web interface, the software incorrectly allows the use of non-ASN1 characters. When the CLI is used, the action is not allowed and an error message is displayed.

CLI

CR_0000145136 When the switch is configured with the `console event critical` setting, the event log output of `show tech all` lists only the critical events. With this fix, `show tech all` lists all event log entries.

CR_0000156237 When a user has enabled Spanning Tree in the CLI and configured a protocol version other than the default MSTP, the CLI Menu does not allow the user to modify Spanning Tree parameters. The menu indicates that the switch requires a reboot. When the switch is actually rebooted the same problem is present after the reboot.

CR_0000160089 When a non-HP transceiver is inserted into the switch, the software generates an error message to alert the user. This error message contained a spelling mistake, which has been corrected: `0533 FFI: port 27 is not a HP HP transceiver. Please go to: www.hp.com/rnd/device_help/2_inform` for more info.

CR_0000161668 After a user has changed the Spanning Tree Protocol Version to RPVST in the CLI Menu, the switch prompts the user to save the configuration and reboot the system to activate the changes. However, after saving and rebooting, those messages continue to be displayed.

CPU Utilization

CR_0000151164 The switch occasionally reports CPU utilization of 99%. This is a false reading and does not affect switch performance.

Crash

CR_0000149153 When an exceptionally large amount of IP Address Manager (IPAM) output is generated by the output of `show tech all` and captured using the `copy command-output CLI` command, the system might crash with the following message: NMI event
SW:IP=0x00147168 MSR:0x02029200 LR:0x00120f7c cr: 0x44000400
sp:0x04d60f30 xer:0x00000000 Task='mSess3' Task ID=0x4d59728.

CR_0000151102 In a rare situation, after a failover to the Standby Management Module (SMM) or the stack's Standby switch, the switch might reboot unexpectedly with a message similar to Software exception at `asicMgrSlaveFilters.c:185` -- in 'mNSA', task ID = 0x1b1fea80 -> Internal Name Server Error.

CR_0000153386 When a large number of 802.1X clients is being authenticated, reconfiguring port security modes such as **learn-mode** might cause the switch to reboot unexpectedly with a message similar to Software exception at `multMgmtUtil.c:88` -- in 'mPpmgrCtrl', task ID = 0x13b1f940 -> Internal error.

CR_0000154769 The switch may reboot unexpectedly when the management interface is accessed via SSH and the `show tech all` CLI command is executed, or when the SSH session is idle following execution of the CLI command `show run` a few minutes earlier.

Display Issue

CR_0000140830 When `terminal length` is changed from the default of 24, the config file display is truncated, and the outputs of `show logging` and `show interfaces` might be interleaved in the output of `show tech all`.

File Transfer

CR_0000148584 A configuration file with a blank community name in the `snmp-server host` entry cannot be downloaded to the switch. Although the switch does not allow the `snmp-server host` entry to be configured with a blank community name, earlier software bugs might cause this condition.

ICMP

CR_0000155702 The switch sends a ping request to a random IP address every 20 minutes.

IPv6

CR_0000140467 The switch does not generate an event log message when IPv6 Neighbor Discovery (ND) detects a duplicate address.

LLDP

CR_0000157298 When a PD sends an LLDP-MED TLV to a switch port in which the PD uses the invalid value of 0 Watts, the switch software actually applies the invalid 0 Watts. This causes the PD to reboot every time it transmits the 0 Watts in the TLV. The switch might log over-current warnings (00562 ports: port <port ID> PD Overcurrent indication) because the PD is already drawing power over the port when the software applies 0 Watts power. The value of 0 Watts in the TLV is henceforth be rejected with the error Invalid power value 0 deciWatts received from MED PD on port <port ID>.

Logging

CR_0000155070 The Alert-Log filter criteria do not work as expected when a substring is used as a filter.

MDI

CR_0000162682 The ports on the 2530 and 2530G series switches have the MDI and MDIX bits reversed. When a port is configured to use MDI, it uses MDIX, and vice versa. This results in ports linking up, or not linking up, contrary to expectations.

Multicast

CR_0000138817 When a multicast stream is sent to a reserved multicast address, a General Query might not be forwarded by the switch, causing clients to be dropped from the multicast stream.

Multiple Symptoms

CR_0000151207 The switch experiences high CPU utilization while idle. Also, a continuous ping to the switch shows that after several pings with quick response there is a ping with much slower response. These symptoms affect only YB-software switches.

PoE

CR_0000155423 POE functionality on all ports is shutting down and staying shut-down. The PoE **Detection Status** field indicates "Disabled. To recover, a reboot/power cycle/manual reset of the ports via software is required. The issue is only on 2530-24G-PoE+ SKU.

Port Connectivity

CR_0000161235 When a Gigabit transceiver is inserted in one of the uplink port bays and the switch is rebooted, after the reboot the adjacent copper port no longer establishes link at 100 Mbps speeds. For example, when the transceiver is inserted into port 51, Ethernet port 49 no longer establishes link at 100 Mbps. When the transceiver is inserted into port 52, the problem occurs with port 50.

RADIUS

CR_0000149657 Configuration of multiple RADIUS servers via SNMP fails if a 'create and wait' mechanism is used.

Routing

CR_0000160655 Switches configured for routing: When a VACL is applied to VLAN X, if a host on VLAN X then pings the switch agent's IP address for VLAN Y, the agent's response IP address is also applied to the VACL, and hosts become unreachable.

Self Test

CR_0000159678 When the switch is rebooted a self test runs on the ports. During the self test Fast Ethernet ports come on-line for a brief moment when a loopback test is executed. Some attached link partners might attempt to negotiate link with the switch port at that time. When the link negotiation fails, the link partner does not establish link once the ports come on-line properly.

SNMP

CR_0000151035 When an SNMP read/query (for example, using iMC or the CLI command `walkMib` or `getMib`) to the SNMP MIB ID: `entPhysicalIsFRU` is directed at a Fan Tray or SFP device, the 3800 series switches do not correctly report that they are Assets and are removable.

CR_0000156209 When a configuration file is downloaded to the switch in which the SNMP community name string for unrestricted access is something other than `unrestricted`, the software resets the access-level to the default `restricted`. Although it is expected behavior to default to

restricted when the string `unrestricted` is not precisely matched, the software has been modified to allow the use of both lower and upper-case characters in the word `unrestricted` when parsing a downloaded configuration file.

SSL

CR_0000162587 SSL Security vulnerability due to 56-bit DES-CBC-SHA. Due to security vulnerability, the cipher DES-CBC-SHA is now unavailable.

SSH

CR_0000165393 When the SSH client has a keepalive mechanism configured that requires a response from the SSH server on the switch, the SSH client terminates the session after the first keepalive packet is transmitted. This happens because the switch drops the client's keepalive packet due to an incorrect packet length calculation. This issue has been observed using an openSSH client with the `ServerAliveInterval` configured and the parameter `want_reply` enabled.

Stacking

CR_0000152463, CR_0000152757 After updating Management Stack Members to some versions of X.15.08.0001 or newer software, the Member switches mistakenly displays additional two configuration lines of SNMPv3 configuration in the running-config if `snmp-server host` is configured on the Commander.

CR_0000152647 When IP stacking is enabled on a switch, the default MTU is lowered from 1500 to 1488 bytes by design. However, after enabling IP stacking, the MTU of the Primary VLAN is not set to 1488 bytes and still **usd** the default 1500 bytes. This results in communication problems with the IP address assigned to the Primary VLAN when packets larger than 1460 bytes had to be transmitted.

Switch Hang

CR_0000154152 If there is an active console session providing output at the time of reboot, the switch might become unresponsive and not complete the reboot without further intervention.

Web Management

CR_0000160654 When 51 or more VLANs are configured on the switch, the web interface does not display any VLAN under the **VLAN Management** and **Multicast IGMP** tabs.

Upgrade information

Upgrading restrictions and guidelines

YA/YB.15.17.0007 uses BootROM YA.15.17 or YB.15.07. If your switch has an older version of BootROM, the BootROM will be updated with this version of software.

For more information about BootROM, see the *HP Switch Software Management and Configuration Guide* for your switch.

-
- ⓘ **IMPORTANT:** During the software update, the switch will automatically boot twice. The switch will update the primary BootROM, then reboot, and then update the secondary BootROM. After the switch flash memory is updated and the final boot is initiated, no additional user intervention is needed. Do not interrupt power to the switch during this important update.
-

Contacting HP

For additional information or assistance, contact HP Networking Support:

www.hp.com/networking/support

Before contacting HP, collect the following information:

- Product model names and numbers
- Technical support registration number (if applicable)
- Product serial numbers
- Error messages
- Operating system type and revision level
- Detailed questions

HP security policy

A Security Bulletin is the first published notification of security vulnerabilities and is the only communication vehicle for security vulnerabilities.

- Fixes for security vulnerabilities are not documented in manuals, release notes, or other forms of product documentation.
- A Security Bulletin is released when all vulnerable products still in support life have publicly available images that contain the fix for the security vulnerability.

To find security bulletins:

1. Go to the HP Support Center website at www.hp.com/go/hpsc.
2. Enter your product name or number and click **Go**.
3. Select your product from the list of results.
4. Click the **Top issues & solutions** tab.
5. Click the **Advisories, bulletins & notices** link.

To initiate a subscription to receive future HP Security Bulletin alerts via email, sign up at:

www4.hp.com/signup_alerts

Related information

Documents

To find related documents, see the HP Support Center website:

www.hp.com/support/manuals

- Enter your product name or number and click **Go**. If necessary, select your product from the resulting list.
- For a complete list of acronyms and their definitions, see *HP FlexNetwork Technology Acronyms*.

Related documents

The following documents provide related information:

- *HP Switch Software Access Security Guide YA/YB.15.17*
- *HP Switch Software Advanced Traffic Management Guide YA/YB.15.17*
- *HP Switch Software Basic Operation Guide*
- *HP Switch Software IPv6 Configuration Guide YA/YB.15.17*
- *HP Switch Software Management and Configuration Guide YA/YB.15.17*
- *HP Switch Software Multicast and Routing Guide YA/YB.15.17*

Websites

- Official HP Home page: www.hp.com
- HP Networking: www.hp.com/go/networking
- HP product manuals: www.hp.com/support/manuals
- HP download drivers and software: www.hp.com/networking/software
- HP software depot: www.software.hp.com
- HP education services: www.hp.com/learn

Documentation feedback

HP is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback (docsfeedback@hp.com). Include the document title and part number, version number, or the URL when submitting your feedback.