



Hewlett Packard Enterprise

HPE ESXi Offline Bundle

HPE Offline bundle for VMware ESXi includes HPE CIM Providers.

It is recommended that customers update to the latest version on supported ProLiant at their earliest convenience.

| Offline Bundle | Components and Versions Included | Release Date |
|---|---|--------------|
| HP Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 10.0.0 | hp-ams-600.10.1.0-32.2159203 hp-smx-limited-600.03.07.00.24-2159203 char-hpilo-600.9.0.2.8-1OEM.600.0.0.2159203 char-hpcru-6.0.6.14-1OEM.600.0.0.2159203 hp-esxi-fc-enablement-550.2.1.8-1198610 | Mar-15 |
| HP ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.1 | hpssacli-2.0.23.0-5.5.0 hpbootcfg-6.0.0.02-01.00.11.2159203 hponcfg-6.0.0.04-00.13.17.2159203 hp-conrep-6.0.0.1-0.0.13.2159203 hptestevent-6.0.0.01-00.00.8.2159203 char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 | Mar-15 |
| HP ESXi Offline Bundle for vSphere 6.0 version 2.1 | char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 hp-smx-provider 600.03.07.00.23-2159203 hp-ams-esx- 600.10.1.0-32.2159203 hp-esxi-fc-enablement- 550.2.1.8-1198610 | Mar-15 |
| HP NMI Sourcing Driver for VMware vSphere 6.0 version 2.3 | hpnmi - 600.2.3.14-2159203 | Mar-15 |
| HP Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 10.1.0 | hp-ams-600.10.1.0-32.2159203 hp-smx-limited-600.03.07.00.24-2159203 char-hpilo-600.9.0.2.8-1OEM.600.0.0.2159203 char-hpcru-6.0.6.14-1OEM.600.0.0.2159203 hp-esxi-fc-enablement-550.2.2.8-1198610 | Mar-15 |
| HP ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.2 | hpssacli-2.10.14.0-6.0.0 hpbootcfg-6.0.0.02-01.00.11.2159203 hponcfg-6.0.0.04-00.13.17.2159203 hp-conrep-6.0.0.1-0.0.13.2159203 hptestevent-6.0.0.01-00.00.8.2159203 char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 | Mar-15 |
| HP ESXi Offline Bundle for vSphere 6.0 version 2.2 | char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 hp-smx-provider 600.03.07.00.23-2159203 hp-ams-esx- 600.10.1.0-32.2159203 hp-esxi-fc-enablement- 550.2.2.8-1198610 | Mar-15 |
| HP Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 10.2.0 | hp-ams-600.10.2.0-22.2159203 hp-smx-limited-600.03.08.00.12-2159203 char-hpilo-600.9.0.2.8-1OEM.600.0.0.2159203 char-hpcru-6.0.6.14-1OEM.600.0.0.2159203 hp-esxi-fc-enablement-550.2.3.12-1198610 | Jun-15 |
| HP ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.3 | hpssacli-2.20.11.0-6.0.0 hpbootcfg-6.0.0.02-01.00.11.2159203 hponcfg-6.0.0.04-00.13.17.2159203 hp-conrep-6.0.0.1-0.0.13.2159203 hptestevent-6.0.0.01-00.00.8.2159203 char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 | Jun-15 |
| HP ESXi Offline Bundle for vSphere 6.0 version 2.3 | char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 hp-smx-provider 600.03.08.00.13-2159203 hp-ams-esx- 600.10.2.0-22.2159203 hp-esxi-fc-enablement- 550.2.3.16-1198610 | Jun-15 |

| Offline Bundle | Components and Versions Included | Release Date |
|---|--|--------------|
| HP ESXi Offline Bundle for vSphere 6.0 version 2.3.50 | char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 hp-smx-provider 600.03.09.00.15-2768847 hp-ams-esx- 600.10.2.0-22.2159203 hp-esxi-fc-enablement- 600.2.3.2-2494585 | Oct-15 |
| HP ESXi Offline Bundle for vSphere 6.0 version 2.4 | char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 hp-smx-provider 600.03.09.00.15-2768847 hp-ams-esx- 600.10.3.0-15.2494585 hp-esxi-fc-enablement- 600.2.4.6-2494585 | Nov-15 |
| HP Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 10.3.0 | hp-ams-600.10.3.0-15.2494585 hp-smx-limited-600.03.09.00.15-2159203 char-hpilo-600.9.0.2.8-1OEM.600.0.0.2159203 char-hpcru-6.0.6.14-1OEM.600.0.0.2159203 hp-esxi-fc-enablement-600.2.4.6-2494585 | Nov-15 |
| HP ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.4 | hpssacli-2.30.6.0-6.0.0 hpbootcfg-6.0.0.02-01.00.11.2159203 hponcfg-6.0.0.04-00.13.17.2159203 hp-conrep-6.0.0.1-0.0.13.2159203 hptestevent-6.0.0.01-00.00.8.2159203 char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 char-hpilo 600.9.0.2.8-1OEM.600.0.0.2159203 | Nov-15 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 2.5 | char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 hpe-ilo 600.10.0.0.26-1OEM.600.0.0.2494585 hpe-smx-provider 600.03.10.00.13-2768847 amsHelper- 600.10.4.0-22.2494585 hpe-esxi-fc-enablement- 600.2.5.20-2494585 | Apr-16 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 10.4.0 | amsHelper-600.10.4.0-22.2494585 hpe-smx-limited-600.03.10.00.12-2768847 hpe-ilo-600.10.0.0.26-1OEM.600.0.0.2494585 char-hpcru-6.0.6.14-1OEM.600.0.0.2159203 hpe-esxi-fc-enablement-600.2.5.20-2494585 | Apr-16 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.5 | hpssacli-2.40.13.0-6.0.0 hpbootcfg-6.0.0.02-02.00.6.2494585 hponcfg-6.0.0.04-00.14.4.2494585 conrep-6.0.0.01-01.00.7.2494585 hptestevent-6.0.0.01-01.00.5.2494585 char-hpcru 6.0.6.14-1OEM.600.0.0.2159203 hpe-ilo 600.10.0.0.26-1OEM.600.0.0.2494585 | Apr-16 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 2.6 | hpe-cru 6.0.8.6-1OEM.600.0.0.2159203 hpe-ilo 600.10.0.0.26-1OEM.600.0.0.2494585 hpe-smx-provider 600.03.11.00.9-2768847 amshelper- 600.10.5.0-24.2494585 hpe-esxi-fc-enablement- 600.2.6.20-2494585 | Oct-16 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 10.5.0 | amshelper-600.10.5.0-24.2494585 hpe-smx-limited-600.03.11.00.11-2768847 hpe-ilo-600.10.0.0.26-1OEM.600.0.0.2494585 hpe-cru-6.0.8.6-1OEM.600.0.0.2494585 hpe-esxi-fc-enablement-600.2.6.20-2494585 | Oct-16 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.6 | hpssacli-2.60.18.0-6.0.0 hpbootcfg-6.0.0.02-02.00.6.2494585 hponcfg-6.0.0.4.4-2.4.2494585 conrep-6.0.0.01-02.00.1.2494585 hptestevent-6.0.0.01-01.00.5.2494585 hpe-cru 6.0.8.6-1OEM.600.0.0.2494585 hpe-ilo 600.10.0.0.26-1OEM.600.0.0.2494585 | Oct-16 |
| HP NMI Sourcing Driver for VMware vSphere 6.0 version 2.4 | hpe-nmi - 600.2.4.16-2494585 | Oct-16 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 2.6 | hpe-cru 650.6.5.8.24-1.4240417 hpe-ilo 650.10.0.1-24.4240417 hpe-smx-provider 650.03.11.00.17-4240417 amshelper- 650.10.6.0-24.4240417 hpe-esxi-fc-enablement- 650.2.6.10-4240417 | Nov-16 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 10.6.0 | amshelper- 650.10.6.0-24.4240417 hpe-smx-limited- 650.03.11.00.13-4240417 hpe-ilo-650.10.0.1-24.4240417 hpe-cru-650.6.5.8.24-1.4240417 hpe-esxi-fc-enablement-650.2.6.10-4240417 | Nov-16 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 2.6 | ssacli-2.60.18.0-6.0.0 hpbootcfg-6.0.0.02-02.00.6.2494585 hponcfg-6.0.0.4.4-2.4.2494585 conrep-6.0.0.01-02.00.1.2494585 hptestevent-6.0.0.01-01.00.5.2494585 hpe-cru 650.6.5.8.24-1.4240417 hpe-ilo 650.10.0.1-24.4240417 | Nov-16 |

| Offline Bundle | Components and Versions Included | Release Date |
|---|--|--------------|
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 2.6a | hpssacli-2.60.18.0-6.0.0 hpbootcfg-6.0.0.02-02.00.6.2494585 hponcfg-6.0.0.4.4-2.4.2494585 conrep-6.0.0.01-02.00.1.2494585 hptestevent-6.0.0.01-01.00.5.2494585 hpe-cru 6.0.8.6-1OEM.600.0.0.2494585 hpe-ilo 600.10.0.0.26-1OEM.600.0.0.2494585 | Feb-17 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 2.6.2 | hpe-cru 650.6.5.8.24-1.4240417 hpe-ilo 650.10.0.2-2.4240417 hpe-smx-provider 650.03.11.00.17-4240417 amshelper- 650.10.6.0-24.4240417 hpe-esxi-fc-enablement- 650.2.6.10-4240417 | May-17 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 2.6.2 | ssacli-2.60.18.0-6.0.0 hpbootcfg-6.0.0.02-02.00.6.2494585 hponcfg-6.0.0.4.4-2.4.2494585 conrep-6.0.0.01-02.00.1.2494585 hptestevent-6.0.0.01-01.00.5.2494585 hpe-cru 650.6.5.8.24-1.4240417 hpe-ilo 650.10.0.2-2.4240417 | May-17 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 10.6.2 | amshelper- 650.10.6.0-24.4240417 hpe-smx-limited- 650.03.11.00.13-4240417 hpe-ilo-650.10.0.2-2.4240417 hpe-cru-650.6.5.8.24-1.4240417 hpe-esxi-fc-enablement-650.2.6.10-4240417 | May-17 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 3.1.0 | cru 6.0.9.8-1OEM.600.0.0.2159203 ilo 600.10.1.0.12-1OEM.600.0.0.2494585 smx-provider 600.03.12.00.17-2768847 amsd- 600.11.1.0-24.2494585 fc-enablement- 600.3.1.0.16-2494585 | Jul-17 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 11.1.0 | amsd-600.11.1.0-24.2494585 smx-limited-600.03.12.00.18-2768847 ilo-600.10.1.0.12-1OEM.600.0.0.2494585 cru-6.0.9.8-1OEM.600.0.0.2494585 fc-enablement-600.3.1.0.16-2494585 | Jul-17 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 3.1 | ssacli-3.10.3.0-6.0.0 bootcfg-6.0.0.02-03.00.5.2494585 hponcfg-6.0.0.5.0-1.5.2494585 conrep-6.0.0.02-00.00.12.2494585 testevent-6.0.0.02-00.00.8.2494585 cru 6.0.9.8-1OEM.600.0.0.2494585 ilo 600.10.1.0.12-1OEM.600.0.0.2494585 | Jul-17 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.1.0 | cru 650.6.5.9.8-1.4240417 ilo 650.10.1.0-12.4240417 smx-provider 650.03.12.00.18-4240417 amsd- 650.11.1.0-24.4240417 fc-enablement- 650.3.1.0.16-4240417 | Jul-17 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 11.1.0 | amsd- 650.11.1.0-24.4240417 smx-limited- 650.03.12.00.17-4240417 ilo-650.10.1.0-12.4240417 cru-650.6.5.9.8-1.4240417 fc-enablement-650.3.1.0.16-4240417 | Jul-17 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 3.1 | ssacli-3.10.3.0-6.5.0 bootcfg-6.0.0.02-03.00.5.2494585 hponcfg-6.0.0.5.0-1.5.2494585 conrep-6.0.0.02-00.00.12.2494585 testevent-6.5.0.02-00.00.16.2494585 cru 650.6.5.9.8-1.4240417 ilo 650.10.1.0-12.4240417 | Jul-17 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.1.1 | cru 650.6.5.9.8-1.4240417 ilo 650.10.1.0-12.4240417 smx-provider 650.03.12.10.1-4240417 amsd- 650.11.1.0-24.4240417 fc-enablement- 650.3.1.0.16-4240417 | Jul-17 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 11.1.5 | amsd-600.11.1.5-16.2494585 smx-limited-600.03.12.50.2-2768847 ilo_ 600.10.1.0.12-1OEM.600.0.0.2494585 cru_ 6.0.9.8-1OEM.600.0.0.2159203 fc-enablement-600.3.1.5.4-2494585 | Oct-17 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 3.1.5 | ssacli-3.10.3.0-6.0.0 bootcfg-6.0.0.02-03.00.5.2494585 hponcfg-6.0.0.5.0-2.2.2494585 conrep-6.0.0.03-00.00.8.2494585 testevent-6.0.0.02-00.00.8.2494585 cru 600.6.5.9.8-1.2494585 ilo 600.10.1.0-12.2494585 | Oct-17 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 3.1.5 | cru 600.6.5.9.8-1.2159203 ilo 600.10.1.0-12.2494585 smx-provider 600.03.12.50.3-2768847 | Oct-17 |

| Offline Bundle | Components and Versions Included | Release Date |
|--|--|--------------|
| | amsd- 600.11.1.5-16.2494585 fc-enablement- 600.3.1.5.4-2494585 | |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 11.1.5 | amsd-650.11.1.5-16.4240417 smx-limited-650.03.12.50.2-4240417 ilo-650.10.1.0-12.4240417 cru-650.6.5.9.8-1.4240417 fc-enablement-650.3.1.5.4-4240417 | Oct-17 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 3.1.5 | ssacli-3.10.3.0-6.5.0 bootcfg-6.0.0.02-03.00.5.2494585 hponcfg-6.0.0.5.0-2.2.2494585 conrep-6.0.0.03-00.00.8.2494585 testevent-6.5.0.02-00.00.16.2494585 cru 650.6.5.9.8-1.4240417 ilo 650.10.1.0-12.4240417 | Oct-17 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.1.5 | cru_650.6.5.9.8-1.4240417 ilo_650.10.1.0-12.4240417 smx-provider-650.03.12.50.2-4240417 amsd-650.11.1.5-16.4240417 fc-enablement-650.3.1.5.4-4240417 | Oct-17 |
| | | |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 11.2.0 | amsd-600.11.2.0-18.2494585 smx-limited-600.03.13.00.4-2768847 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 cru_6.0.9.8-1OEM.600.0.0.2159203 fc-enablement-600.3.2.0.12-2494585 | Feb-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 3.2.0 | ssacli-3.25.4.0-6.0.0 bootcfg-6.0.0.02-03.00.5.2494585 hponcfg-6.0.0.5.0-2.2.2494585 conrep-6.0.0.03-01.00.2.2494585 testevent-6.0.0.02-00.00.8.2494585 cru 6.0.9.8-1OEM.600.0.0.2494585 ilo 600.10.1.0-12.2494585 | Feb-18 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 3.2.0 | 6.0.9.8-1OEM.600.0.0.2159203 ilo 600.10.1.0-12.2494585 smx-provider 600.03.13.00.5-2768847 amsd- 600.11.2.0-18.2494585 fc-enablement- 600.3.2.0.12-2494585 | Feb-18 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 11.2.0 | amsd-650.11.2.0-18.4240417 smx-limited-650.03.13.00.4-4240417 ilo-650.10.1.0-12.4240417 cru-650.6.5.9.8-1.4240417 fc-enablement-650.3.2.0.12-4240417 | Feb-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 3.2.0 | ssacli-3.25.4.0-6.5.0 bootcfg-6.0.0.02-03.00.5.2494585 hponcfg-6.0.0.5.0-2.2.2494585 conrep-6.0.0.03-01.00.2.2494585 testevent-6.5.0.02-00.00.16.4240417 cru 650.6.5.9.8-1.4240417 ilo 650.10.1.0-12.4240417 | Feb-18 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.2.0 | cru_650.6.5.9.8-1.4240417 ilo_650.10.1.0-12.4240417 smx-provider-650.03.13.00.6-4240417 amsd-650.11.2.0-18.4240417 fc-enablement-650.3.2.0.12-4240417 | Feb-18 |
| | | |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.7 version 11.2.0 | amsd- 670.11.2.0-12.7535516 smx-limited- 670.03.13.00.3-7535516 ilo- 670.10.1.0.16-1 cru- 670.6.7.10.14-1 fc-enablement- 670.3.20.12-7535516 | Apr-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.7 version 3.2.0 | ssacli - 3.25.4.0-6.5.0 bootcfg- 6.7.0.02-04.00.4 hponcfg - 6.7.0.5.0-3.8 testevent - 6.7.0.02-00.01.12 conrep - 6.7.0.03-01.00.2 ilo - 670.10.1.0.16 cru - 670.6.7.10.14 | Apr-18 |
| HPE ESXi Offline Bundle for vSphere 6.7 version 3.2.0 | cru - 670.6.7.10.14 ilo - 670.10.1.0.16 smx-provider - 670.03.13.00.5 fc-enablement - 670.3.20.12 amsd- 670.11.2.0-12 | Apr-18 |
| | | |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 11.3.0 | amsd-600.11.3.0-12.2494585 smx-limited-600.03.14.00.3-2768847 ilo_600.10.1.0.12-1 cru_6.0.9.8-1 fc-enablement-600.3.3.0.10-2494585 | Jun-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 3.3.0 | ssacli-3.30.14.0-6.0.0 bootcfg-6.0.0.02-05.00.10.2494585 hponcfg-6.0.0.5.3-0.2.2494585 | Jun-18 |

| Offline Bundle | Components and Versions Included | Release Date |
|---|---|--------------|
| | conrep-6.0.0.03-02.00.2.2494585 testevent-6.0.0.02-00.00.8.2494585 cru 6.0.9.8-1 ilo 600.10.1.0-12-1 | |
| HPE ESXi Offline Bundle for vSphere 6.0 version 3.3.0 | cru - 6.0.9.8-1 ilo 600.10.1.0-12-1 smx-provider 600.03.14.00.3-2768847 amsd- 600.11.3.0-12.2494585 fc-enablement- 600.3.3.0.10-2494585 | Jun-18 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 11.3.0 | amsd-650.11.3.0-10.4240417 smx-limited-650.03.14.00.3-4240417 ilo- 650.10.3.0.2-1 cru- 650.6.5.10.4-1 fc-enablement-650.3.3.0.10-4240417 | Jun-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 3.3.0 | ssacli-3.30.14.0-6.5.0 bootcfg-6.0.0.02-05.00.10.2494585 hponcfg-6.0.0.5.3-0.2.2494585 conrep-6.0.0.03-02.00.2.2494585 testevent-6.5.0.02-00.00.16.4240417 cru 650.6.5.10.4-1 ilo 650.10.3.0.2-1 | Jun-18 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.3.0 | cru_650.6.5.10.4-1 ilo_650.10.3.0.2-1 smx-provider-650.03.14.00.3-4240417 amsd-650.11.3.0-10.4240417 fc-enablement-650.3.2.0.12-4240417 | Jun-18 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.7 version 11.3.0 | amsd- 670.11.3.0-10.7535516 smx-limited- 670.03.14.00.3-7535516 ilo- 670.10.1.0.16-1 cru- 670.6.7.10.14-1 fc-enablement- 670.3.20.12-7535516 | Jun-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.7 version 3.3.0 | ssacli - 3.30.14.0-6.7.0 bootcfg- 6.7.0.02-05.00.4 hponcfg - 6.7.0.5.3-0.2 testevent - 6.7.0.02-00.01.12 conrep - 6.7.0.03-02.00.1 ilo- 670.10.1.0.16-1 cru - 670.6.7.10.14-1 | Jun-18 |
| HPE ESXi Offline Bundle for vSphere 6.7 version 3.3.0 | cru - 670.6.7.10.14-1 ilo - 670.10.1.0.16-1 smx-provider - 670.03.14.00.2 fc-enablement - 670.3.20.12 amsd- 670.11.3.0-10 | Jun-18 |
| | | |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0 version 11.3.0 | amsd-600.11.3.0-12.2494585 smx-limited-600.03.14.00.3-2768847 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 cru_6.0.9.8-1OEM.600.0.0.2159203 fc-enablement-600.3.3.0.10-2494585 | Sep-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 3.3.0 | bootcfg-6.0.0.02-05.00.10.2494585 conrep-6.0.0.03-02.00.2.2494585 cru_6.0.9.8-1OEM.600.0.0.2494585 hponcfg-6.0.0.5.3-0.2.2494585 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 ssacli-3.30.14.0-6.0.0.2494585 testevent-6.0.0.02-00.00.8.2494585 | Sep-18 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 3.3.0 | smx-provider-600.03.14.00.3-2768847 amsd-600.11.3.0-12.2494585 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 cru_6.0.9.8-1OEM.600.0.0.2159203 fc-enablement-600.3.3.0.10-2494585 | Sep-18 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 11.3.0 | amsd-650.11.3.0-10.4240417 smx-limited-650.03.14.00.3-4240417 ilo_650.10.3.0.2-1OEM.650.0.0.4240417 cru_650.6.5.10.4-1OEM.650.0.0.4240417 fc-enablement-650.3.3.0.10-4240417 | Sep-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 3.3.0 | bootcfg-6.0.0.02-05.00.10.2494585 conrep-6.0.0.03-02.00.2.2494585 cru_650.6.5.10.4-1OEM.650.0.0.4240417 hponcfg-6.0.0.5.3-0.2.2494585 ilo_650.10.3.0.02-1OEM.650.0.0.4240417 ssacli-3.30.14.0-6.5.0 testevent-6.5.0.02-00.00.16.4240417 | Sep-18 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.3.0 | smx-provider-650.03.14.00.3-4240417 amsd-650.11.3.0-10.4240417 ilo_650.10.3.0.2-1OEM.650.0.0.4240417 cru_650.6.5.10.4-1OEM.650.0.0.4240417 fc-enablement-650.3.3.0.10-4240417 | Sep-18 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.7 version 11.3.5 | amsd-670.11.3.5-6.7535516 smx-limited-670.03.14.00.3-7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 | Sep-18 |

| Offline Bundle | Components and Versions Included | Release Date |
|----------------|--|--------------|
| | cru_670.6.7.10.14-1OEM.670.0.0.7535516 | |

| Offline Bundle | Components and Versions Included | Release Date |
|---|---|--------------|
| | fc-enablement-670.3.20.12-7535516 | |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.7 version 3.3.0 | bootcfg-6.7.0.02-05.00.4.7535516 conrep-6.7.0.03-02.00.1.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 hponcfg-6.7.0.5.3-0.2.7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 ssacli-3.30.14.0-6.7.0 testevent-6.7.0.02-00.01.12.7535516 | Sep-18 |
| HPE ESXi Offline Bundle for vSphere 6.7 version 3.3.5 | smx-provider-670.03.14.00.2-7535516 amsd-670.11.3.5-6.7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 fc-enablement-670.3.20.12-7535516 | Sep-18 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.7 version 11.3.5 | amsd-670.11.3.5-6.7535516 smx-limited-670.03.14.00.3-7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 fc-enablement-670.3.20.12-7535516 | Oct-18 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.7 version 3.3.0 | bootcfg-6.7.0.02-05.00.4.7535516 conrep-6.7.0.03-02.00.1.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 hponcfg-6.7.0.5.3-0.2.7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 ssacli-3.30.14.0-6.7.0 testevent-6.7.0.02-00.01.12.7535516 | Oct-18 |
| HPE ESXi Offline Bundle for vSphere 6.7 version 3.3.5 | smx-provider-670.03.14.00.2-7535516 amsd-670.11.3.5-6.7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 fc-enablement-670.3.20.12-7535516 | Oct-18 |
| HPE Agentless Management Service Offline Bundle VMware vSphere 6.0 version 11.4.0 | amsd-600.11.4.0-18.2494585 smx-limited-600.03.15.00.1-2768847 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 cru_6.0.9.8-1OEM.600.0.0.2159203 fc-enablement-600.3.4.0.10-2494585 | Apr-19 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0 version 3.4.0 | bootcfg-6.0.0.02-05.00.10.2494585 conrep-6.0.0.03-03.00.10.2494585 cru_6.0.9.8-1OEM.600.0.0.2494585 hponcfg-6.0.0.5.4-0.3.2494585 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 ssacli-3.40.3.0-6.0.0 testevent-6.0.0.02-00.00.8.2494585 | Apr-19 |
| HPE ESXi Offline Bundle for vSphere 6.0 version 3.4.0 | smx-provider-600.03.15.00.2-2768847 amsd-600.11.4.0-18.2494585 ilo_600.10.1.0.12-1OEM.600.0.0.2494585 cru_6.0.9.8-1OEM.600.0.0.2159203 fc-enablement-600.3.4.0.10-2494585 | Apr-19 |
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5 version 11.4.0 | amsd-650.11.4.0-18.4240417 smx-limited-650.03.15.00.1-4240417 ilo_650.10.3.0.2-1OEM.650.0.0.4240417 cru_650.6.5.10.4-1OEM.650.0.0.4240417 fc-enablement-650.3.4.0.10-4240417 | Apr-19 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5 version 3.4.0 | bootcfg-6.0.0.02-05.00.10.2494585 conrep-6.0.0.03-03.00.10.2494585 cru_650.6.5.10.4-1OEM.650.0.0.4240417 hponcfg-6.0.0.5.4-0.3.2494585 ilo_650.10.3.0.2-1OEM.650.0.0.4240417 ssacli-3.40.3.0-6.5.0 testevent-6.5.0.02-00.00.16.4240417 | Apr-19 |
| HPE ESXi Offline Bundle for vSphere 6.5 version 3.4.0 | smx-provider-650.03.15.00.4-4240417 amsd-650.11.4.0-18.4240417 ilo_650.10.3.0.2-1OEM.650.0.0.4240417 cru_650.6.5.10.4-1OEM.650.0.0.4240417 fc-enablement-650.3.4.0.10-4240417 | Apr-19 |

| Offline Bundle | Components and Versions Included | Release Date |
|--|---|--------------|
| HPE Agentless Management Service Offline Bundle for VMware vSphere 6.7 version 11.4.0 | amsd-670.11.4.0-18.7535516 smx-limited-670.03.15.00.2-7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 fc-enablement-670.3.40.10-7535516 | Apr-19 |
| HPE ESXi Utilities Offline Bundle for VMware vSphere 6.7 version 3.4.0 | bootcfg-6.7.0.02-05.00.4.7535516 conrep-6.7.0.03-03.00.11.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 hponcfg-6.7.0.5.4-0.3.7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 ssacli-3.40.3.0-6.7.0 testevent-6.7.0.02-00.01.12.7535516 | Apr-19 |
| HPE ESXi Offline Bundle for vSphere 6.7 version 3.4.0 | smx-provider-670.03.15.00.3-7535516 amsd-670.11.4.0-18.7535516 ilo_670.10.1.0.16-1OEM.670.0.0.7535516 cru_670.6.7.10.14-1OEM.670.0.0.7535516 fc-enablement-670.3.40.10-7535516 | Apr-19 |
| | | |

© Copyright 2015 Hewlett-Packard Enterprise Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

November 2015

